



AUDI Q3: 1FFW099

Vinnumber:	WAUZZZ8U6DR106377	Versionname:	Q3 140PK
First Registrationdate:	18/06/2013	Fiscalpower:	
Expertise Mileage:	123884	Power Kw:	103
Bodytype:	SUV	Body color	Light Blue
Gearbox:	MAN 6 VIT	Paint type	Metalic
Transmission:		Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Battery functioning	Yes	Parking lot	3425
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		

Options

Radio CD	Central consol F	
Windows electric F	Rear parking sensors	
Windows electric R	Type of Tow bar	No Tow bar
Cruise Control		
Steering wheel multifunctional		
Seats F heated		
Radio multimedia		
Type of headlighting	Headlighting Halogen	
Type of GPS	GPS big screen color	
Type of Lining	Lining leather	
Type of climate control	Autom climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

Summer tyres:	215/65/16/98 V LightMetal			
	Fr.L.	Continental: 4 mm	Fr.R.	Continental: 4 mm
	Re.L.	Bridgestone: 5 mm	Re.R.	Bridgestone: 5 mm



Assistance equipment

Emergency spare wheel	Yes
-----------------------	------------

Total cost ex VAT	150,00
Ignition key, Missing, E - Replace	150,00



Bonnet, Bad repair, Acceptable	0,00
--------------------------------	------



Door R L, Scratch(es), 67 - Polish	0,00
------------------------------------	------

No pictures to display

Sill outer R, Scratch(es), Acceptable	0,00
---------------------------------------	------

No pictures to display


Door F R, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display


GPS, Not functioning (well), Forfeit	0,00
--------------------------------------	------



Tailgate, Bad repair, Acceptable	0,00
----------------------------------	------



Roof, Bad repair, Acceptable	0,00
------------------------------	------



Door R R, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display