



VOLVO V60: 1LHT198

Vinnumber:	YV1FW74C1G1301999	Versionname:	2.0 D2 KINETIC
First Registrationdate:	1/10/2015	Fiscalpower:	
Expertise Mileage:	187822	Power Kw:	88
Bodytype:		Body color	Black
Gearbox:	MAN 6 VIT	Paint type	Metalic
Transmission:	Front	Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Maintenance	NOT OK	Parking lot	4201
Maintenance	UITVOEREN		
Battery functioning	Yes		
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		

Options

Radio CD		Central consol F	
GPS storage	HD	Luggage cover	
GPS storage		Rear parking sensors	
Windows electric F		Type of Tow bar	No Tow bar
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

Summer tyres:	215/55/16/93 V LightMetal			
	Fr.L.	Michelin: 3 mm	Fr.R.	Michelin: 3 mm
	Re.L.	Michelin: 4 mm	Re.R.	Michelin: 4 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	1541,59
Wing R R, Dent(s), PDR - Paintless dent repair	63,00




Door F R, Dent(s) and scratch(es), LI - Repair and paint (complete)

366,35



Door R L, Dent(s) and scratch(es), Acceptable

0,00



Alloy rim F R, Scratch(es), LI - Repair and paint (complete)

95,00



Door F L, Scratch(es), Acceptable

0,00



Armrest lid F Mid, Incomplete, E - Replace

25,00



Interior, Stain, Cleaning

100,00



Alloy rim R L, Scratch(es), LI - Repair and paint (complete)

95,00



A-Pillar left, Dent(s), Acceptable

0,00



Door panel R R, Scratch(es), Smart repair

110,64



Door R R, Scratch(es), Acceptable

0,00



Wing F L, Scratch(es), 67 - Polish

0,00



Steering wheel, Worn, Acceptable

0,00



Alloy rim F L, Scratch(es), LI - Repair and paint (complete)

95,00



Bumper R, Scratch(es), LI - Repair and paint (complete)

211,80



Maintenance, Maintenance, Execute

0,00



Bumper F, Scratch(es), LI - Repair and paint (complete)

211,80





Door panel R L, Scratch(es), Acceptable 0,00



Bonnet, Dent(s), Acceptable 0,00



Wing R L, Scratch(es), Acceptable 0,00



Rearview mirror R complete, Scratch(es), E - Replace 168,00

