



VOLKSWAGEN SHARAN: 1JPP949			
Vinnumber:	WVWZZZ7NZFV027338	Versionname:	2.0 CR TDI 103KW HIGHLINE BMT
First Registrationdate:	2/02/2015	Fiscalpower:	
Expertise Mileage:	120640	Power Kwr:	103
Bodytype:		Body color	Dark Blue
Gearbox:	MAN 6 VIT	Paint type	Metalic
Transmission:	Front	Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Maintenance	28.200 KM OU 347 JOURS	Parking lot	4332
Maintenance	OK		
Battery functioning	Yes		
Number of doors	5		
Number of seats	7		
Number head rests	9		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options			
Radio CD		Seats electric F L	
GPS storage	HD	Seats electric F R	
GPS storage		Sun Roof electric	
Windows electric F		Panoramic roof	
Windows electric R		Central consol F	
Cruise Control		Luggage cover	
Steering wheel multifunctional		Front parking sensors	
Seats F heated		Rear parking sensors	
Radio multimedia		Type of Tow bar	Tow bar fixed
Type of headlighting	Headlighting Xenon		
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		
Type of climate control	Autom climate control		

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear				
Summer tyres:	225/50/17/98 H LightMetal			
	Fr.L.	Continental: 7 mm	Fr.R.	Continental: 7 mm
	Re.L.	Continental: 7 mm	Re.R.	Continental: 7 mm

Assistance equipment	
	Runflat
	Yes
Total cost ex VAT	
1136,93	
Door F R, Dent(s), Acceptable	
0,00	
No pictures to display	
Wing R L, Dent(s) and scratch(es), Acceptable	
0,00	
No pictures to display	
Wing F R, Dent(s) and scratch(es), Acceptable	
0,00	

No pictures to display

Alloy rim R R polished, Scratch(es), Acceptable	0,00
---	------

No pictures to display

Sliding door R, Dent(s) and scratch(es), LI - Repair and paint (complete)	762,85
---	--------



Alloy rim R L polished, Scratch(es), LI - Repair and paint (complete)	95,00
---	-------



Alloy rim F L polished, Scratch(es), LI - Repair and paint (complete)	95,00
---	-------



Wing R R, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Alloy rim F R polished, Scratch(es), Acceptable	0,00
---	------

No pictures to display

Ignition key, Missing, E - Replace	150,00
------------------------------------	--------



Door R L, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Outer door handle F R, Scratch(es), Acceptable	0,00
--	------

No pictures to display

Bonnet, Stone chip(s), Acceptable	0,00
-----------------------------------	------

No pictures to display

Bumper grille, Broken, E - Replace	34,08
------------------------------------	-------

