



VOLVO V60: 1KVR909

Vinnumber:	YV1FW74C1G1293568	Versionname:	2.0 D2 KINETIC
First Registrationdate:	15/07/2015	Fiscalpower:	
Expertise Mileage:	115631	Power Kw:	88
Bodytype:	Break	Body color:	Silver
Gearbox:	MAN 6 VIT	Paint type:	Metallic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3819
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	Rear parking sensors
Cruise Control	Type of Tow bar
Steering wheel multifunctional	Tow bar fixed
Seats F heated	
Radio multimedia	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining semi-leather
Type of climate control	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

Summer tyres:	215/55/16/97 W LightMetal			
	Fr.L.	Bridgestone: 6 mm	Fr.R.	Bridgestone: 6 mm
	Re.L.	Bridgestone: 7 mm	Re.R.	Bridgestone: 7 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
Total cost ex VAT			1048,76
Alloy rim F R, Scratch(es), LI - Repair and paint (complete)			95,00



Bumper F, Scratch(es), LI - Repair and paint (complete)

211,80



Bonnet, Chemical polution, LI - Repair and paint (complete)

290,08



Armrest R M, Hole, Smart repair

64,32



Ignition key, Missing, E - Replace

0,00



Wing R L, Scratch(es), Acceptable

0,00

No pictures to display

Rocker panel inner F R, Dent(s), LI - Repair and paint (complete)

115,56



Alloy rim R R, Scratch(es), LI - Repair and paint (complete)

95,00





Wing F R, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Door F L, Dent(s), PDR - Paintless dent repair	63,00
--	-------



Door panel F L, Damaged, E - Replace	114,00
--------------------------------------	--------

