



VOLVO V40: 1GQG283

Vinnumber:	YV1MV8481E2146280	Versionname:	V40 D2 Base 115PK
First Registrationdate:	1/04/2014	Fiscalpower:	
Expertise Mileage:	155426	Power Kw:	84
Bodytype:		Body color	Dark Grey
Gearbox:	MAN 6 VIT	Paint type	Metalic
Transmission:	Front	Rims summer	Steel
Fueltype:	Diesel	Oil level	OK
Battery functioning	Yes	Parking lot	4525
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Steel		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options

Radio CD	Central consol F	
Windows electric F	Luggage cover	
Windows electric R	Rear parking sensors	
Cruise Control	Type of Tow bar	No Tow bar
Steering wheel multifunctional		
Radio multimedia		
Type of headlighting	Headlighting Halogen	
Type of GPS	GPS big screen color	
Type of Lining	Lining semi-artificial leather	
Type of climate control	Manual climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	195/65/15/91 H Steel			
Summer tyres:	Fr.L.	Bridgestone: 3 mm	Fr.R.	Bridgestone: 3 mm
	Re.L.	Bridgestone: 4 mm	Re.R.	Bridgestone: 4 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	1163,26
Windscreen, Repaired, Acceptable	0,00
No pictures to display	
Roof, Dent(s), Acceptable	0,00
No pictures to display	
Roof, Chemical polution, LI - Repair and paint (complete)	481,50



Door R L, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Floor covering F L, Worn, Smart repair	64,32
--	-------



Bonnet, Chemical polution, LI - Repair and paint (complete)	290,08
---	--------



Door R R, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Bumper F, Dent(s) and scratch(es), LI - Repair and paint (complete)	211,80
---	--------



Rear spoiler, Chemical polution, LI - Repair and paint (complete)	115,56
---	--------

