



**VOLVO V60: 1LSV655**

|                                   |                          |              |                        |
|-----------------------------------|--------------------------|--------------|------------------------|
| Vinnumber:                        | <b>YV1FW74C1G1310521</b> | Versionname: | <b>2.0 D2 MOMENTUM</b> |
| First Registrationdate:           | <b>25/11/2015</b>        | Fiscalpower: |                        |
| Expertise Mileage:                | <b>64184</b>             | Power Kw:    | <b>88</b>              |
| Bodytype:                         | <b>Break</b>             | Body color   | <b>Dark Blue</b>       |
| Gearbox:                          | <b>MAN 6 VIT</b>         | Paint type   | <b>Metallic</b>        |
| Transmission:                     |                          | Rims summer  | <b>Aluminium</b>       |
| Fueltype:                         | <b>Diesel</b>            | Oil level    | <b>OK</b>              |
| Battery functioning               | <b>Yes</b>               | Parking lot  | <b>1126</b>            |
| Number of doors                   | <b>5</b>                 |              |                        |
| Number of seats                   | <b>5</b>                 |              |                        |
| Number head rests                 | <b>5</b>                 |              |                        |
| Rims summer                       | <b>Aluminium</b>         |              |                        |
| Category                          | <b>Passenger Car</b>     |              |                        |
| Oil level                         | <b>OK</b>                |              |                        |
| Registration Certificate Car (BE) | <b>Yes</b>               |              |                        |

**Options**

|                                |                              |
|--------------------------------|------------------------------|
| Radio CD                       | Central consol F             |
| Windows electric F             | Luggage cover                |
| Windows electric R             | Rear parking sensors         |
| Cruise Control                 | Type of Tow bar              |
| Steering wheel multifunctional | <b>No Tow bar</b>            |
| Radio multimedia               |                              |
| Type of headlighting           | <b>Headlighting Halogen</b>  |
| Type of GPS                    | <b>GPS big screen color</b>  |
| Type of Lining                 | <b>Lining leather</b>        |
| Type of climate control        | <b>Autom climate control</b> |

**Limited Technical Inspection**

|                     |           |                     |            |
|---------------------|-----------|---------------------|------------|
| Airco functioning   | <b>OK</b> | Battery functioning | <b>Yes</b> |
| Tires wear profile  | <b>OK</b> | Power steering      | <b>Yes</b> |
| Idle position       | <b>OK</b> | Sound engine        | <b>OK</b>  |
| Engine startingtime | <b>OK</b> | Clutch test         | <b>OK</b>  |
| Exhaust gass        | <b>OK</b> | Wiper fluid level   | <b>OK</b>  |
| Handbrake           | <b>OK</b> | Transmission        | <b>OK</b>  |
|                     |           | Lighting            | <b>OK</b>  |
|                     |           | Wiperblades         | <b>OK</b>  |

**Degree of wear**

|               |                           |                |       |                |
|---------------|---------------------------|----------------|-------|----------------|
| Summer tyres: | 215/50/17/95 W LightMetal |                |       |                |
|               | Fr.L.                     | Semperit: 8 mm | Fr.R. | Semperit: 8 mm |
|               | Re.L.                     | Michelin: 5 mm | Re.R. | Michelin: 5 mm |

**Assistance equipment**

|            |           |            |           |
|------------|-----------|------------|-----------|
| Repair kit | <b>No</b> | Compressor | <b>No</b> |
|------------|-----------|------------|-----------|

|                                  |                |
|----------------------------------|----------------|
| Total cost ex VAT                | <b>1148,33</b> |
| Door F R, Bad repair, Acceptable | <b>0,00</b>    |



Rearview mirror L complete, Broken, Le - Replace and paint

283,00



Roof, Dent(s), PDR - Paintless dent repair

63,00



Alloy rim F R, Scratch(es), LI - Repair and paint (complete)

95,00



Alloy rim R R, Scratch(es), LI - Repair and paint (complete)

95,00



Alloy rim R L, Scratch(es), LI - Repair and paint (complete)

95,00



Bumper R, Scratch(es), LI - Repair and paint (complete)

211,80





Door R R, Bad repair, Acceptable

0,00



Door F L, Scratch(es), Acceptable

0,00

No pictures to display

Alloy rim F L, Scratch(es), LI - Repair and paint (complete)

95,00



Wing R R, Bad repair, Acceptable

0,00



Compressor, Missing, E - Replace

0,00

No pictures to display

Tyre repair kit, Missing, E - Replace

210,53

