



VOLVO V60: 1JJS483

Vinnumber:	YV1FW8481F1250687	Versionname:	1.6 D2 KINETIC
First Registrationdate:	6/01/2015	Fiscalpower:	
Expertise Mileage:	91627	Power Kw:	84
Bodytype:		Body color	Blue
Gearbox:	MAN 6 VIT	Paint type	Metalic
Transmission:	Front	Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Maintenance	SERVICE IN 10292KM 4M	Parking lot	1408
Maintenance	OK		
Battery functioning	Yes		
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options

Radio CD	Central consol F
GPS storage	Luggage cover
GPS storage	HD Rear parking sensors
Windows electric F	
Windows electric R	
Cruise Control	
Steering wheel multifunctional	
Radio multimedia	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining fabrics
Type of climate control	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

Summer tyres:	205/60/16/92 H LightMetal			
	Fr.L.	Bridgestone: 5 mm	Fr.R.	Bridgestone: 5 mm
	Re.L.	Bridgestone: 6 mm	Re.R.	Bridgestone: 5 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	591,80
-------------------	---------------

Rearview mirror housing L, Scratch(es), Acceptable	0,00
--	-------------

Outer valance R, Scratch(es), Acceptable	0,00
--	-------------

No pictures to display

Seat cover F L, Stain, Acceptable	0,00
No pictures to display	
Alloy rim F L, Scratch(es), LI - Repair and paint (complete)	95,00
	
Bumper F, Scratch(es), LI - Repair and paint (complete)	211,80
	
Alloy rim R L, Scratch(es), LI - Repair and paint (complete)	95,00
	
Door R L, Dent(s), Acceptable	0,00
No pictures to display	
Alloy rim F R, Scratch(es), LI - Repair and paint (complete)	95,00
	
Alloy rim R R, Scratch(es), LI - Repair and paint (complete)	95,00
	