


VOLVO V60: 1KFJ354

Vinnumber:	YV1FW8481F1261386	Versionname:	1.6 D2 KINETIC
First Registrationdate:	21/04/2015	Fiscalpower:	
Expertise Mileage:	158164	Power Kw:	84
Bodytype:	Break	Body color:	Silver
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	2227
Maintenance:	2951KM - 2 MAANDEN		
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Central consol F	
GPS storage	Luggage cover	
GPS storage	Rear parking sensors	
Windows electric F	Type of Tow bar	No Tow bar
Windows electric R		
Cruise Control		
Steering wheel multifunctional		
Radio multimedia		
Type of headlighting	Headlighting Halogen	
Type of GPS	GPS big screen color	
Type of Lining	Lining fabrics	
Type of climate control	Autom climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	205/60/16/96 H LightMetal			
Winter tyres:	Fr.L.	Vredestein: 6 mm	Fr.R.	Vredestein: 6 mm
	Re.L.	Vredestein: 8 mm	Re.R.	Vredestein: 8 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
Total cost ex VAT			1486,66
Wing R L, Scratch(es), Acceptable			0,00
<i>No pictures to display</i>			
Bumper F, Scratch(es), LI - Repair and paint (complete)			211,80



Ceiling, Stain, Cleaning

25,00



Alloy rim R R, Scratch(es), LI - Repair and paint (complete)

95,00



Door panel R R, Tear, Acceptable

0,00

No pictures to display

Seat cover R L, Stain, Cleaning

25,00



Windscreen, Stone chip(s), Windscreen repair

58,80



Alloy rim F R, Scratch(es), LI - Repair and paint (complete)

95,00



Door frame F L, Dent(s), LI - Repair and paint (partial)

125,00



Door F L, Scratch(es), Acceptable

0,00

No pictures to display

Alloy rim R L, Scratch(es), LI - Repair and paint (complete)

95,00



Wing R R, Dent(s), Acceptable

0,00

No pictures to display

Bonnet, Dent(s), Acceptable	0,00
No pictures to display	
Door R L, Scratch(es), Acceptable	0,00
No pictures to display	
Sill outer R, Scratch(es), LI - Repair and paint (complete)	310,50
	
Roof, Scratch(es), Acceptable	0,00
No pictures to display	
Seat cover F R, Stain, Cleaning	25,00
	
Door panel F L, Tear, E - Replace	114,00
	
Rocker panel inner F L, Dent(s), LI - Repair and paint (complete)	211,56
	
Bumper R, Scratch(es), Acceptable	0,00
No pictures to display	
Alloy rim F L, Scratch(es), LI - Repair and paint (complete)	95,00
	