


VOLVO V40 CROSS COUNTRY: 1JNA259

Vinnumber:	YV1MZ8451F2070549	Versionname:	1.6 D2 SUMMUM
First Registrationdate:	20/01/2015	Fiscalpower:	
Expertise Mileage:	88643	Power Kw:	84
Bodytype:		Body color	Red
Gearbox:	MAN 6 VIT	Paint type	Metalic
Transmission:		Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Battery functioning	Yes	Parking lot	3627
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options

Radio CD	Panoramic roof
Windows electric F	Central consol F
Windows electric R	Luggage cover
Cruise Control	Rear parking sensors
Steering wheel multifunctional	Type of Tow bar
Seats F heated	No Tow bar
Radio multimedia	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining leather
Type of climate control	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

Summer tyres:	225/50/17/98 Y LightMetal			
	Fr.L.	Continental: 7 mm	Fr.R.	Continental: 7 mm
	Re.L.	Bridgestone: 5 mm	Re.R.	Bridgestone: 5 mm

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
Total cost ex VAT			0,00
Wing R R, Dent(s), Acceptable			0,00
<i>No pictures to display</i>			
Door R R, Bad repair, Acceptable			0,00



Rear spoiler, Bad repair, Acceptable

0,00



Door F R, Scratch(es), Acceptable

0,00

No pictures to display

Bumper R, Bad repair, Acceptable

0,00



Wing R R, Bad repair, Acceptable

0,00



Wing R L, Scratch(es), Acceptable

0,00

No pictures to display

Bonnet, Bad repair, Acceptable

0,00



Bumper F, Bad repair, Acceptable

0,00

