



RENAULT Scenic: 1HHD245

Vinnumber:	VF1JZNA0651159004	Versionname:	SCENIC Bose Ed.130PK
First Registrationdate:	22/07/2014	Fiscalpower:	
Expertise Mileage:	132094	Power Kw:	96
Bodytype:		Body color	Grey
Gearbox:	MAN 6 VIT	Paint type	Metalic
Transmission:	Front	Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Maintenance	OK	Parking lot	4833
Battery functioning	Yes		
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options

Radio CD		Sun Roof electric	
GPS storage	SD	Panoramic roof	
GPS storage		Central consol F	
Windows electric F		Luggage cover	
Windows electric R		Front parking sensors	
Cruise Control		Rear parking sensors	
Steering wheel multifunctional		Type of Tow bar	No Tow bar
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining semi-artificial leather		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

205/55/17/95 V LightMetal				
Summer tyres:	Fr.L.	Continental: 7 mm	Fr.R.	Continental: 7 mm
	Re.L.	Continental: 8 mm	Re.R.	Continental: 8 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
Total cost ex VAT			380,00
Alloy rim R L polished, Chemical polution, LI - Repair and paint (complete)			95,00



Wing R L, Scratch(es), Acceptable 0,00

No pictures to display

Ignition key, Not functioning (well), Acceptable 0,00



Alloy rim R R polished, Chemical polution, LI - Repair and paint (complete) 95,00



Bumper corner R L, Scratch(es), Acceptable 0,00

No pictures to display

Door R L, Scratch(es), Acceptable 0,00

No pictures to display

Bonnet, Stone chip(s), Acceptable 0,00

No pictures to display

Wing F R, Scratch(es), Acceptable 0,00

No pictures to display

Door F R, Dent(s), Acceptable 0,00

No pictures to display

Alloy rim F L polished, Chemical polution, LI - Repair and paint (complete) 95,00



Molding trunk, Not original part, P - Check 0,00



Alloy rim F R polished, Chemical polution, LI - Repair and paint (complete) 95,00



Seat cover F L, Worn, P - Check 0,00

