



PEUGEOT Expert: 1GSD287

Vinnumber:	VF3XSAHZ8EZ017070	Versionname:	EXPERT B/F SWB 227 L1H1 128PK
First Registrationdate:	14/04/2014	Fiscalpower:	
Expertise Mileage:	141267	Power Kw:	94
Bodytype:	Transporter	Body color:	Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:		Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	TRU11
Number of doors:	5		
Number of seats:	3		
Number head rests:	3		
Rims summer:	Steel		
Category:	Light Commercial Vehicle		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Rear parking sensors	
Windows electric F		Type of Tow bar	Tow bar fixed
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Manual climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

Summer tyres:	205/65/16/107 T Steel			
	Fr.L.	Michelin: 6 mm	Fr.R.	Michelin: 6 mm
	Re.L.	Michelin: 6 mm	Re.R.	Michelin: 6 mm

Assistance equipment

Spare wheel	Yes
-------------	-----

Total cost ex VAT	1540,20
Wing F R, Dent(s) and scratch(es), LI - Repair and paint (complete)	165,13





Bonnet, Dent(s), Acceptable	0,00
-----------------------------	------

No pictures to display

Bumper R, Deformed / Strained, E - Replace	329,40
--	--------



Bumper F, Scratch(es), Smart repair	110,64
-------------------------------------	--------



Headlight R, Broken, E - Replace	321,00
----------------------------------	--------



Sill outer R, Dent(s) and scratch(es), LI - Repair and paint (complete)	232,88
---	--------



Ignition key, Missing, E - Replace	150,00
------------------------------------	--------

No pictures to display

Wing R R, Dent(s) and scratch(es), LI - Repair and paint (complete)	231,15
---	--------

