



JEEP CHEROKEE: 1WQK148

Vinnumber:	1C4PJMDY7EW307883	Versionname:	2.0 MJD 140HP LIMITED 4WD
First Registrationdate:	30/03/2015	Fiscalpower:	
Expertise Mileage:	148521	Power Kw:	103
Bodytype:	SUV	Body color	Grey
Gearbox:	MAN 6 VIT	Paint type	Metalic
Transmission:	4 Wheel	Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Battery functioning	Yes	Parking lot	3727
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options

GPS storage	HD	Seats electric F L	
GPS storage		Seats F L ventilated	
Windows electric F		Seats F R ventilated	
Windows electric R		Sun Roof electric	
Cruise Control		Panoramic roof	
Steering wheel multifunctional		Central consol F	
Seats F heated		Luggage cover	
Radio multimedia		Front parking sensors	
Type of headlighting	Headlighting Xenon	Rear parking sensors	
Type of GPS	GPS big screen color	Type of Tow bar	Tow bar removable
Type of Lining	Lining leather		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

Winter tyres:	225/55/18/98 H LightMetal			
	Fr.L.	Pirelli: 3 mm	Fr.R.	Pirelli: 3 mm
	Re.L.	Bridgestone: 7 mm	Re.R.	Bridgestone: 7 mm

Assistance equipment

Spare wheel	Yes
Number of charging cables (normal)	0
Number of charging cables (rapid charge)	0

Total cost ex VAT	1349,24
-------------------	---------

Tailgate, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display	
------------------------	--

Door F L, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display	
------------------------	--

Rocker panel inner R R, Dent(s), LI - Repair and paint (complete)		115,56
		
Alloy rim F R, Scratch(es), LI - Repair and paint (complete)		95,00
		
Bumper F M, Scratch(es), Acceptable		0,00
No pictures to display		
Alloy rim F L, Scratch(es), LI - Repair and paint (complete)		95,00
		
Bumper R, Scratch(es), Smart repair		110,64
		
Protection plate M, Deformed / Strained, E - Replace		74,00
		
Rocker panel inner R L, Scratch(es), Acceptable		0,00
No pictures to display		
Door F R, Scratch(es), Acceptable		0,00
No pictures to display		
Wing R L, Scratch(es), Acceptable		0,00
No pictures to display		
Door R R, Dent(s) and scratch(es), LI - Repair and paint (complete)		382,02



Door R L, Dent(s) and scratch(es), LI - Repair and paint (complete)

382,02



Alloy rim R L, Rust, Acceptable

0,00



Alloy rim R R, Scratch(es), LI - Repair and paint (complete)

95,00

