


**PEUGEOT 508: 1FQT830**

|                                    |                          |              |                                           |
|------------------------------------|--------------------------|--------------|-------------------------------------------|
| Vinnumber:                         | <b>VF38E9HD8DL047727</b> | Versionname: | <b>508 SW e-HDi Active BMP 115PK Aut.</b> |
| First Registrationdate:            | <b>26/09/2013</b>        | Fiscalpower: |                                           |
| Expertise Mileage:                 | <b>183621</b>            | Power Kw:    | <b>84</b>                                 |
| Bodytype:                          | <b>Break</b>             | Body color:  | <b>Dark Blue</b>                          |
| Gearbox:                           | <b>MAN 6 VIT</b>         | Paint type:  | <b>Metallic</b>                           |
| Transmission:                      |                          | Rims summer: | <b>Aluminium</b>                          |
| Fueltype:                          | <b>Diesel</b>            | Oil level:   | <b>OK</b>                                 |
| Battery functioning:               | <b>Yes</b>               | Parking lot: | <b>4308</b>                               |
| Number of doors:                   | <b>5</b>                 |              |                                           |
| Number of seats:                   | <b>5</b>                 |              |                                           |
| Number head rests:                 | <b>5</b>                 |              |                                           |
| Rims summer:                       | <b>Aluminium</b>         |              |                                           |
| Category:                          | <b>Passenger Car</b>     |              |                                           |
| Oil level:                         | <b>OK</b>                |              |                                           |
| Registration Certificate Car (BE): | <b>Yes</b>               |              |                                           |

**Options**

|                                |                              |                   |
|--------------------------------|------------------------------|-------------------|
| Radio CD                       | Panoramic roof               |                   |
| Windows electric F             | Central consol F             |                   |
| Windows electric R             | Luggage cover                |                   |
| Cruise Control                 | Front parking sensors        |                   |
| Steering wheel multifunctional | Rear parking sensors         |                   |
| Radio multimedia               | Type of Tow bar              | <b>No Tow bar</b> |
| Type of headlighting           | <b>Headlighting Halogen</b>  |                   |
| Type of GPS                    | <b>GPS big screen color</b>  |                   |
| Type of Lining                 | <b>Lining fabrics</b>        |                   |
| Type of climate control        | <b>Autom climate control</b> |                   |
| Head-up Display                |                              |                   |

**Limited Technical Inspection**

|                     |           |                     |            |
|---------------------|-----------|---------------------|------------|
| Airco functioning   | <b>OK</b> | Battery functioning | <b>Yes</b> |
| Tires wear profile  | <b>OK</b> | Power steering      | <b>Yes</b> |
| Idle position       | <b>OK</b> | Sound engine        | <b>OK</b>  |
| Engine startingtime | <b>OK</b> | Clutch test         | <b>OK</b>  |
| Exhaust gass        | <b>OK</b> | Wiper fluid level   | <b>OK</b>  |
| Handbrake           | <b>OK</b> | Transmission        | <b>OK</b>  |
|                     |           | Lighting            | <b>OK</b>  |
|                     |           | Wiperblades         | <b>OK</b>  |

**Degree of wear**

|               |                                  |                       |       |                       |
|---------------|----------------------------------|-----------------------|-------|-----------------------|
|               | <b>215/60/16/99 T LightMetal</b> |                       |       |                       |
| Winter tyres: | Fr.L.                            | <b>Michelin: 3 mm</b> | Fr.R. | <b>Michelin: 3 mm</b> |
|               | Re.L.                            | <b>Goodyear: 3 mm</b> | Re.R. | <b>Goodyear: 3 mm</b> |

**Assistance equipment**

|                                       |            |      |                |
|---------------------------------------|------------|------|----------------|
| Spare wheel                           | <b>Yes</b> | Jack | <b>Yes</b>     |
| Total cost ex VAT                     |            |      | <b>1932,99</b> |
| Rear window, Scratch(es), E - Replace |            |      | <b>370,00</b>  |



Door R L, Scratch(es), Acceptable

0,00

No pictures to display

Alloy rim F R, Scratch(es), LI - Repair and paint (complete)

95,00



Windscreen, Stone chip(s), Acceptable

0,00



Rearview mirror housing L, Broken, LI - Repair and paint (complete)

115,56



Bumper R, Dent(s) and scratch(es), LI - Repair and paint (complete)

211,80



Door R R, Dent(s) and scratch(es), LI - Repair and paint (complete)

318,35





|                                        |      |
|----------------------------------------|------|
| Maintenance book, Missing, E - Replace | 0,00 |
|----------------------------------------|------|

No pictures to display


|                                        |      |
|----------------------------------------|------|
| Alloy rim F L, Scratch(es), Acceptable | 0,00 |
|----------------------------------------|------|

No pictures to display

|                                |      |
|--------------------------------|------|
| Roof, Scratch(es), 67 - Polish | 0,00 |
|--------------------------------|------|

No pictures to display

|                                                             |        |
|-------------------------------------------------------------|--------|
| Bonnet, Chemical polution, LI - Repair and paint (complete) | 290,08 |
|-------------------------------------------------------------|--------|



|                                       |       |
|---------------------------------------|-------|
| Protection plate M, Tear, E - Replace | 74,00 |
|---------------------------------------|-------|



|                                                                     |        |
|---------------------------------------------------------------------|--------|
| Wing R R, Dent(s) and scratch(es), LI - Repair and paint (complete) | 308,20 |
|---------------------------------------------------------------------|--------|



|                                    |        |
|------------------------------------|--------|
| Ignition key, Missing, E - Replace | 150,00 |
|------------------------------------|--------|

No pictures to display