



MERCEDES B: 1JXD364

Vinnumber:	WDD2462121J316241	Versionname:	1.5 B 180 CDI BLUEEFF STYLE EDITION
First Registrationdate:	11/03/2015	Fiscalpower:	
Expertise Mileage:	54005	Power Kw:	80
Bodytype:		Body color	Black
Gearbox:	MAN 6 VIT	Paint type	Metalic
Transmission:	Front	Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Maintenance	SERVICE B5 -26D	Parking lot	4333
Maintenance	NOT OK		
Battery functioning	Yes		
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options

Radio CD	Central consol F
GPS storage	Luggage cover
GPS storage	SD
Windows electric F	
Windows electric R	
Cruise Control	
Steering wheel multifunctional	
Radio multimedia	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining fabrics
Type of climate control	Manual climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

Summer tyres:	205/55/16/91 H LightMetal			
	Fr.L.	Firestone: 6 mm	Fr.R.	Firestone: 6 mm
	Re.L.	Dunlop: 7 mm	Re.R.	Dunlop: 7 mm

Assistance equipment

Repair kit	Yes	Compressor	No
------------	-----	------------	----

Total cost ex VAT	2768,85
-------------------	---------

Alloy rim R R, Scratch(es), Acceptable	0,00
--	------

No pictures to display

Wing R L, Dent(s) and scratch(es), LI - Repair and paint (complete)	404,20
---	--------



Alloy rim F R, Scratch(es), LI - Repair and paint (complete)

95,00



Bonnet, Dent(s), LI - Repair and paint (complete)

338,08



Wing F L, Scratch(es), LI - Repair and paint (complete)

220,18



Door R L, Dent(s), PDR - Paintless dent repair

63,00



Alloy rim F L, Scratch(es), LI - Repair and paint (complete)

95,00



Maintenance, Maintenance, Execute

0,00



Sill trim L, Scratch(es), It - Spot repair

115,56



Door F L, Scratch(es), LI - Repair and paint (complete)

318,35



Bumper R, Dent(s) and scratch(es), LI - Repair and paint (complete)

283,80



Alloy rim R L, Scratch(es), LI - Repair and paint (complete)

95,00



Door F R, Scratch(es), LI - Repair and paint (complete)

318,35



Wing F R, Dent(s) and scratch(es), Acceptable

0,00

No pictures to display

Door R R, Scratch(es), Acceptable

0,00

No pictures to display

Bumper F, Scratch(es), LI - Repair and paint (complete)

211,80



Compressor, Missing, E - Replace

210,53

