


BMW 3: 1JVG768

Vinnumber:	WBA3K91050F936703	Versionname:	3 TOURING 316d 116PK
First Registrationdate:	13/11/2014	Fiscalpower:	
Expertise Mileage:	101310	Power Kw:	85
Bodytype:		Body color	Black
Gearbox:	MAN 6 VIT	Paint type	Metalic
Transmission:	Back	Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Maintenance	OK	Parking lot	4804
Maintenance	SERVICE IN 25000KM 1 2020		
Battery functioning	Yes		
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options

Radio CD	Central consol F
GPS storage	HD Luggage cover
GPS storage	
Windows electric F	
Windows electric R	
Steering wheel multifunctional	
Radio multimedia	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining artificial leather
Type of climate control	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

Summer tyres:	205/60/16/92 V LightMetal			
	Fr.L.	Vredestein: 7 mm	Fr.R.	Vredestein: 7 mm
	Re.L.	Bridgestone: 4 mm	Re.R.	Bridgestone: 3 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	613,60
Bumper F, Scratch(es), LI - Repair and paint (complete)	211,80



Door R L, Dent(s) and scratch(es), Acceptable	0,00
No pictures to display	
Alloy rim F R, Scratch(es), LI - Repair and paint (complete)	95,00



Seat cover F L, Worn, Acceptable	0,00
No pictures to display	
Bumper R, Scratch(es), LI - Repair and paint (complete)	211,80



Door R R, Repaired, Acceptable	0,00
No pictures to display	
Door F L, Dent(s), Acceptable	0,00
No pictures to display	
Wing R R, Repaired, Acceptable	0,00
No pictures to display	
Sill trim L, Scratch(es), Acceptable	0,00
No pictures to display	
Wing R L, Scratch(es), Acceptable	0,00
No pictures to display	
Alloy rim R L, Scratch(es), LI - Repair and paint (complete)	95,00

