


BMW 3 TOURING: 1KSE030

Vinnumber:	WBA3K11060F840127	Versionname:	2.0 318D (100KW) TOURING
First Registrationdate:	22/06/2015	Fiscalpower:	
Expertise Mileage:	59293	Power Kw:	100
Bodytype:		Body color	Dark Blue
Gearbox:	MAN 6 VIT	Paint type	Metalic
Transmission:	Back	Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Battery functioning	Yes	Parking lot	3733
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options

Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	Front parking sensors
Cruise Control	Rear parking sensors
Steering wheel multifunctional	Type of Tow bar
Seats F heated	No Tow bar
Radio multimedia	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining artificial leather
Type of climate control	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

205/60/16/92 W LightMetal			
Summer tyres:	Fr.L.	Pirelli: 4 mm	Fr.R.
	Re.L.	Pirelli: 4 mm	Re.R.
		Pirelli: 4 mm	

Assistance equipment

Number of charging cables (normal)	0	Runflat	Yes
Number of charging cables (rapid charge)	0		

Total cost ex VAT	327,36
Bumper R, Scratch(es), LI - Repair and paint (complete)	211,80



Door F L, Scratch(es), Acceptable	0,00
No pictures to display	
Alloy rim F R, Scratch(es), Acceptable	0,00
No pictures to display	
Wing R L, Scratch(es), Acceptable	0,00
No pictures to display	
Bumper F, Dent(s), It - Spot repair	115,56

