



|                                   |                   |              |                                  |
|-----------------------------------|-------------------|--------------|----------------------------------|
| CITROEN C4 Picasso: 1GMK933       |                   |              |                                  |
| Vinnumber:                        | VF73A9HC8EJ566286 | Versionname: | GR.C4 PICASSO Business GPS 115PK |
| First Registrationdate:           | 11/03/2014        | Fiscalpower: |                                  |
| Expertise Mileage:                | 103227            | Power Kw:    | 85                               |
| Bodytype:                         | MPV               | Body color   | Grey                             |
| Gearbox:                          | MAN 6 VIT         | Paint type   | Metallic                         |
| Transmission:                     | Front             | Rims summer  | Aluminium                        |
| Fueltype:                         | Diesel            | Oil level    | OK                               |
| Battery functioning               | Yes               | Parking lot  | 2504                             |
| Number of doors                   | 5                 |              |                                  |
| Number of seats                   | 7                 |              |                                  |
| Number head rests                 | 7                 |              |                                  |
| Rims summer                       | Aluminium         |              |                                  |
| Category                          | Passenger Car     |              |                                  |
| Oil level                         | OK                |              |                                  |
| Registration Certificate Car (BE) | Yes               |              |                                  |

|                                |                       |                      |                   |
|--------------------------------|-----------------------|----------------------|-------------------|
| Options                        |                       |                      |                   |
| Radio CD                       |                       | Central consol F     |                   |
| GPS storage                    | HD                    | Rear parking sensors |                   |
| GPS storage                    |                       | Type of Tow bar      | Tow bar removable |
| Windows electric F             |                       |                      |                   |
| Windows electric R             |                       |                      |                   |
| Cruise Control                 |                       |                      |                   |
| Steering wheel multifunctional |                       |                      |                   |
| Radio multimedia               |                       |                      |                   |
| Type of headlighting           | Headlighting Halogen  |                      |                   |
| Type of GPS                    | GPS big screen color  |                      |                   |
| Type of Lining                 | Lining fabrics        |                      |                   |
| Type of climate control        | Autom climate control |                      |                   |

|                              |    |                     |     |
|------------------------------|----|---------------------|-----|
| Limited Technical Inspection |    |                     |     |
| Airco functioning            | OK | Battery functioning | Yes |
| Tires wear profile           | OK | Power steering      | Yes |
| Idle position                | OK | Sound engine        | OK  |
| Engine startingtime          | OK | Clutch test         | OK  |
| Exhaust gass                 | OK | Wiper fluid level   | OK  |
| Handbrake                    | OK | Transmission        | OK  |
|                              |    | Lighting            | OK  |
|                              |    | Wiperblades         | OK  |

|                |                           |                |       |                |
|----------------|---------------------------|----------------|-------|----------------|
| Degree of wear |                           |                |       |                |
| Summer tyres:  | 205/60/16/92 V LightMetal |                |       |                |
|                | Fr.L.                     | Michelin: 5 mm | Fr.R. | Michelin: 5 mm |
|                | Re.L.                     | Michelin: 5 mm | Re.R. | Michelin: 5 mm |

|                                          |     |
|------------------------------------------|-----|
| Assistance equipment                     |     |
| Emergency spare wheel                    | Yes |
| Number of charging cables (normal)       | 0   |
| Number of charging cables (rapid charge) | 0   |

|                                                   |         |
|---------------------------------------------------|---------|
| Total cost ex VAT                                 | 2532,91 |
| Bumper F, Crack, LI - Repair and paint (complete) | 211,80  |



Alloy rim R R, Scratch(es), LI - Repair and paint (complete)

95,00



Door R R, Dent(s), Acceptable

0,00

No pictures to display

Wing F R, Scratch(es), LI - Repair and paint (complete)

220,18



Door F L, Scratch(es), Acceptable

0,00

No pictures to display

Rearview mirror R complete, Bad repair, Repair/replace (lump sum)

0,00

No pictures to display

Door F R, Scratch(es), Acceptable

0,00

No pictures to display

Door R L, Dent(s) and scratch(es), LI - Repair and paint (complete)

318,35



Tailgate, Scratch(es), Acceptable

0,00

No pictures to display

Protection plate M, Deformed / Strained, E - Replace

108,00



Wing F L, Scratch(es), Acceptable


0,00



|                                   |      |
|-----------------------------------|------|
| wing R L, Scratch(es), Acceptable | 0,00 |
|-----------------------------------|------|

No pictures to display

|                                                           |        |
|-----------------------------------------------------------|--------|
| Roof, Chemical polution, LI - Repair and paint (complete) | 529,50 |
|-----------------------------------------------------------|--------|



|                                                    |      |
|----------------------------------------------------|------|
| Rearview mirror housing L, Scratch(es), Acceptable | 0,00 |
|----------------------------------------------------|------|

No pictures to display

|                                                         |        |
|---------------------------------------------------------|--------|
| Bumper R, Scratch(es), LI - Repair and paint (complete) | 211,80 |
|---------------------------------------------------------|--------|



|                                                             |        |
|-------------------------------------------------------------|--------|
| Bonnet, Chemical polution, LI - Repair and paint (complete) | 290,08 |
|-------------------------------------------------------------|--------|



|                                                                     |        |
|---------------------------------------------------------------------|--------|
| Wing R L, Dent(s) and scratch(es), LI - Repair and paint (complete) | 308,20 |
|---------------------------------------------------------------------|--------|





Luggage space cover, Missing, E - Replace

240,00

