



FORD S Max: 1JJR453

|                                   |                   |              |                                   |
|-----------------------------------|-------------------|--------------|-----------------------------------|
| Vinnumber:                        | WF05XXGBWSEA11536 | Versionname: | S-MAX Trend Style St/St DPF 115PK |
| First Registrationdate:           | 6/01/2015         | Fiscalpower: |                                   |
| Expertise Mileage:                | 94326             | Power Kw:    | 85                                |
| Bodytype:                         |                   | Body color   | Grey                              |
| Gearbox:                          | MAN 6 VIT         | Paint type   | Metalic                           |
| Transmission:                     | Front             | Rims summer  | Aluminium                         |
| Fueltype:                         | Diesel            | Oil level    | OK                                |
| Maintenance                       | GEEN MELDING      | Parking lot  | 1524                              |
| Maintenance                       | OK                |              |                                   |
| Battery functioning               | Yes               |              |                                   |
| Number of doors                   | 5                 |              |                                   |
| Number of seats                   | 5                 |              |                                   |
| Number head rests                 | 5                 |              |                                   |
| Rims summer                       | Aluminium         |              |                                   |
| Category                          | Passenger Car     |              |                                   |
| Oil level                         | OK                |              |                                   |
| Registration Certificate Car (BE) | Yes               |              |                                   |

Options

|                                |                       |                       |
|--------------------------------|-----------------------|-----------------------|
| Radio CD                       |                       | Seats electric F L    |
| GPS storage                    | HD                    | Central consol F      |
| GPS storage                    |                       | Luggage cover         |
| Windows electric F             |                       | Front parking sensors |
| Windows electric R             |                       | Rear parking sensors  |
| Cruise Control                 |                       |                       |
| Steering wheel multifunctional |                       |                       |
| Radio multimedia               |                       |                       |
| Type of headlighting           | Headlighting Halogen  |                       |
| Type of GPS                    | GPS big screen color  |                       |
| Type of Lining                 | Lining fabrics        |                       |
| Type of climate control        | Autom climate control |                       |

Limited Technical Inspection

|                     |    |                     |     |
|---------------------|----|---------------------|-----|
| Airco functioning   | OK | Battery functioning | Yes |
| Tires wear profile  | OK | Power steering      | Yes |
| Idle position       | OK | Sound engine        | OK  |
| Engine startingtime | OK | Clutch test         | OK  |
| Exhaust gass        | OK | Wiper fluid level   | OK  |
| Handbrake           | OK | Transmission        | OK  |
|                     |    | Lighting            | OK  |
|                     |    | Wiperblades         | OK  |

Degree of wear

|               |                           |                  |       |                  |
|---------------|---------------------------|------------------|-------|------------------|
| Summer tyres: | 215/60/16/99 H LightMetal |                  |       |                  |
|               | Fr.L.                     | Vredestein: 7 mm | Fr.R. | Vredestein: 7 mm |
|               | Re.L.                     | Vredestein: 7 mm | Re.R. | Vredestein: 8 mm |

Assistance equipment

|            |     |            |     |
|------------|-----|------------|-----|
| Repair kit | Yes | Compressor | Yes |
|------------|-----|------------|-----|

|                   |       |
|-------------------|-------|
| Total cost ex VAT | 65,00 |
|-------------------|-------|

|                                   |      |
|-----------------------------------|------|
| Bumper F, Scratch(es), Acceptable | 0,00 |
|-----------------------------------|------|

|                        |  |
|------------------------|--|
| No pictures to display |  |
|------------------------|--|

|                                   |      |
|-----------------------------------|------|
| Door R R, Scratch(es), Acceptable | 0,00 |
|-----------------------------------|------|

|                        |  |
|------------------------|--|
| No pictures to display |  |
|------------------------|--|

|                                                                                   |  |       |
|-----------------------------------------------------------------------------------|--|-------|
| Wheel bolt cover F R, Missing, E - Replace                                        |  | 10,00 |
|   |  |       |
| Door F R, Scratch(es), Acceptable                                                 |  | 0,00  |
| No pictures to display                                                            |  |       |
| Wheel bolt cover F L, Missing, E - Replace                                        |  | 5,00  |
|  |  |       |
| Wheel bolt cover R L, Missing, E - Replace                                        |  | 25,00 |
|  |  |       |
| Wheel bolt cover R R, Missing, E - Replace                                        |  | 25,00 |
|  |  |       |
| Bonnet, Scratch(es), Acceptable                                                   |  | 0,00  |
| No pictures to display                                                            |  |       |