



VOLKSWAGEN GOLF VII: 1LET131

Vinnumber:	WVWZZZAUZGW092363	Versionname:	1.6 TDI 81KW TRENDLINE
First Registrationdate:	8/09/2015	Fiscalpower:	
Expertise Mileage:	71570	Power Kw:	81
Bodytype:	Hatchback	Body color:	Black
Gearbox:	MAN 5 VIT	Paint type:	Metallic
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	4513
Maintenance:	OVER 7100 KM		
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

GPS storage	SD	Central consol F	
GPS storage		Front parking sensors	
Windows electric F		Rear parking sensors	
Cruise Control		Type of Tow bar	No Tow bar
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	195/65/15/91 T Steel			
Winter tyres:	Fr.L.	Continental: 2 mm	Fr.R.	Continental: 2 mm
	Re.L.	Vredestein: 5 mm	Re.R.	Vredestein: 5 mm

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
Total cost ex VAT			2036,74
Wheel cover F R, Scratch(es), E - Replace			30,00





Bumper R, Scratch(es), LI - Repair and paint (complete)

211,80



Rearview mirror housing R, Scratch(es), LI - Repair and paint (complete)

115,56



Seat cover R, Stain, Cleaning

25,00



Tires, Out of tolerance, P - Check

0,00



Wheel cover F R, Scratch(es), E - Replace

30,00



Tailgate, Scratch(es), LI - Repair and paint (complete)

301,68



Wheel cover R R, Scratch(es), E - Replace

30,00



Seat cover F R, Stain, Cleaning

25,00



Bonnet, Dent(s), PDR - Paintless dent repair

63,00



Wheel cover F L, Scratch(es), Acceptable

0,00



Door R R, Chemical pollution, LI - Repair and paint (complete)

318,35



Wing R R, Dent(s) and scratch(es), LI - Repair and paint (complete)

356,20



Window handle F L, Not functioning (well), P - Check

0,00



Door F R, Scratch(es), LI - Repair and paint (complete)

318,35

