



VOLKSWAGEN CADDY: 1PGN653

Vinnumber:	WV2ZZZ2KZHX009397	Versionname:	
First Registrationdate:	30/06/2016	Fiscalpower:	
Expertise Mileage:	96422	Power Kw:	92
Bodytype:	MPV	Body color	Grey
Gearbox:	Automatic	Paint type	Metalic
Transmission:	Front	Rims summer	Aluminium
Fueltype:	Petrol	Oil level	OK
Battery functioning	Yes	Parking lot	3632
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options

Radio CD	Central consol F
Windows electric F	Luggage cover
Cruise Control	Rear parking sensors
Steering wheel multifunctional	Type of Tow bar
Radio multimedia	Tow bar removable
Type of headlighting	Headlighting Halogen
Type of GPS	No GPS
Type of Lining	Lining fabrics
Type of climate control	Manual climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

205/55/16/94 H LightMetal			
Summer tyres:	Fr.L.	Hankook: 5 mm	Fr.R.
	Re.L.	Hankook: 5 mm	Re.R.

Assistance equipment

Spare wheel	Yes	Jack	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		


Total cost ex VAT	1333,64
Tailgate, Dent(s) and scratch(es), LI - Repair and paint (complete)	410,02



Door F R, Dent(s), Acceptable 0,00

No pictures to display

Trunk lid covering R, Scratch(es), Smart repair 110,64




Bumper R, Scratch(es), LI - Repair and paint (complete) 158,85



Bumper F, Scratch(es), LI - Repair and paint (complete) 158,85



Wing R L, Dent(s) and scratch(es), LI - Repair and paint (complete) 231,15



Door R R, Scratch(es), Acceptable 0,00

No pictures to display

Protection plate M, Deformed / Strained, E - Replace 74,00



Wing F L, Scratch(es), LI - Repair and paint (complete)	165,13
---	--------



Door F L, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Wing F R, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Interior, Dirty, Chemical cleaning	25,00
------------------------------------	-------

