



MERCEDES C: 1HFS963

Vinnumber:	WDD2042021G178082	Versionname:	C BRE 220 CDI BlueEFF. S&S 163PK
First Registrationdate:	9/07/2014	Fiscalpower:	
Expertise Mileage:	115472	Power Kw:	120
Bodytype:	Break	Body color:	Dark Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:		Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2101
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	Front parking sensors
Steering wheel multifunctional	Rear parking sensors
Seats F heated	Type of Tow bar
Radio multimedia	Tow bar removable
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining leather
Type of climate control	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	225/45/17/91 Y LightMetal			
Summer tyres:	Fr.L.	Firestone: 5 mm	Fr.R.	Firestone: 5 mm
	Re.L.	Vredestein: 5 mm	Re.R.	Vredestein: 5 mm

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
-----------------------	------------	------	------------

Total cost ex VAT	760,80
Bumper F, Scratch(es), LI - Repair and paint (complete)	211,80



Alloy rim R L, Scratch(es), LI - Repair and paint (complete) 95,00



Rearlight R , Broken, E - Replace 114,00



Ignition key, Missing, E - Replace 150,00




Alloy rim R R, Scratch(es), LI - Repair and paint (complete) 95,00



Tailgate, Dent(s) and scratch(es), Le - Replace and paint 0,00



Alloy rim F L, Scratch(es), LI - Repair and paint (complete) 95,00



Bonnet, Dent(s), Acceptable 0,00

No pictures to display

Door F L, Scratch(es), Acceptable 0,00

No pictures to display

Wing R R, Dent(s) and scratch(es), Le - Replace and paint 0,00





Bumper R, Dent(s) and scratch(es), Le - Replace and paint

0,00

