



BMW 3: 1GQH151

Vinnumber:	WBA3D91060J413990	Versionname:	3 BER 316d 116PK
First Registrationdate:	1/04/2014	Fiscalpower:	
Expertise Mileage:	122371	Power Kw:	85
Bodytype:	Berline	Body color:	Brown
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Back	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	4304
Number of doors:	4		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F	
GPS storage	HD	Rear parking sensors	
GPS storage		Type of Tow bar	No Tow bar
Windows electric F			
Windows electric R			
Cruise Control			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

205/60/16/92 W LightMetal				
Summer tyres:	Fr.L.	Michelin: 5 mm	Fr.R.	Michelin: 5 mm
	Re.L.	Michelin: 5 mm	Re.R.	Michelin: 5 mm

Assistance equipment


Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	2411,11
Bumper R, Scratch(es), LI - Repair and paint (complete)	211,80



Door R R, Dent(s) and scratch(es), LI - Repair and paint (complete)

318,35



Tailgate, Scratch(es), LI - Repair and paint (complete)

301,68



Alloy rim R R, Scratch(es), Acceptable

0,00

No pictures to display

Ignition key, Missing, E - Replace

0,00

No pictures to display

Rearlight R , Crack, E - Replace

114,00





Alloy rim F R, Scratch(es), LI - Repair and paint (complete) 95,00



Door F R, Scratch(es), Acceptable 0,00

No pictures to display

Bumper F R, Scratch(es), LI - Repair and paint (complete) 211,80



Floor covering F L, Burned, E - Replace 252,00



Door R L, Scratch(es), Acceptable 0,00

No pictures to display

Wing R L, Dent(s) and scratch(es), LI - Repair and paint (complete) 308,20



Bonnet, Dent(s), LI - Repair and paint (complete) 290,08



Wing R R, Dent(s) and scratch(es), LI - Repair and paint (complete)

308,20

