



BMW 5: 1HLY981

Vinnumber:	WBA5L31040D677619	Versionname:	5 TOURING 520d 163PK
First Registrationdate:	25/08/2014	Fiscalpower:	
Expertise Mileage:	101135	Power Kw:	120
Bodytype:		Body color:	Blue
Gearbox:	MAN 6 VIT	Paint type:	Metallic
Transmission:	Back	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	9000KM	Parking lot:	3509
Maintenance:	OK		
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Windows electric F	Central consol F
Windows electric R	Luggage cover
Cruise Control	Front parking sensors
Steering wheel multifunctional	Rear parking sensors
Radio multimedia	Type of Tow bar
Type of headlighting	
Type of GPS	Headlighting Xenon
Type of Lining	GPS big screen color
Type of climate control	Lining leather
	Autom climate control
	Tow bar fixed

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

225/55/17/97 Y LightMetal			
Summer tyres:	Fr.L.	Michelin: 5 mm	Fr.R.
	Re.L.	Michelin: 4 mm	Re.R.
			Michelin: 4 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
Total cost ex VAT			1082,97
Alloy rim F L, Scratch(es), Acceptable			0,00
No pictures to display			
Rearview mirror housing L, Scratch(es), Acceptable			0,00
No pictures to display			
Wing R R, Dent(s), Acceptable			0,00
No pictures to display			
Alloy rim F R, Scratch(es), Acceptable			0,00

Alloy rim F R, Scratch(es), Acceptable		0,00
No pictures to display		
Door F L, Dent(s), Acceptable		0,00
No pictures to display		
Door R R, Repaired, P - Check		0,00
		
Sill trim L, Dent(s) and scratch(es), It - Spot repair		163,56
		
Bumper R, Scratch(es), LI - Repair and paint (complete)		254,16
		
Bumper F, Dent(s) and scratch(es), LI - Repair and paint (complete)		254,16
		
Bonnet, Scratch(es), LI - Repair and paint (complete)		348,09
		
Roof, Dent(s), PDR - Paintless dent repair		63,00
		