


MERCEDES A: 1PRR204

Vinnumber:	WDD1760121J514203	Versionname:	A 180 d BlueEFFICIENCY Edition
First Registrationdate:	31/08/2016	Fiscalpower:	
Expertise Mileage:	52444	Power Kw:	80
Bodytype:		Body color	Grey
Gearbox:	MAN 6 VIT	Paint type	Metallic
Transmission:	Front	Rims summer	Steel
Fueltype:	Diesel	Oil level	OK
Battery functioning	Yes	Parking lot	3713
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Steel		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options

Radio CD		Central consol F	
GPS storage	SD	Luggage cover	
GPS storage		Type of Tow bar	No Tow bar
Windows electric F			
Windows electric R			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Manual climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	195/65/15/95 V Steel			
Winter tyres:	Fr.L.	Michelin: 4 mm	Fr.R.	Michelin: 4 mm
	Re.L.	Michelin: 5 mm	Re.R.	Michelin: 5 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	725,62
Wheel cover F R, Scratch(es), E - Replace	30,00



Wing R R, Bad repair, Acceptable

0,00



Wheel cover F L, Scratch(es), E - Replace

30,00



Door F L, Scratch(es), Acceptable

0,00

No pictures to display

Wheel cover R L, Scratch(es), E - Replace

30,00



Trunk lid covering R, Scratch(es), Acceptable

0,00

No pictures to display

Door panel R R, Scratch(es), Acceptable

0,00

No pictures to display

Door R R, Scratch(es), Acceptable

0,00

No pictures to display

Bonnet, Dent(s), PDR - Paintless dent repair

63,00



Wing F R, Scratch(es), LI - Repair and paint (complete)

220,18



Bumper R, Scratch(es), LI - Repair and paint (complete)

211,80



Wing R L, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Wheel cover R R, Scratch(es), E - Replace	30,00
---	-------



Rear window, Scratch(es), Acceptable	0,00
--------------------------------------	------



Bumper cover R M, Scratch(es), Smart repair	110,64
---	--------



Door F R, Repaired, Acceptable	0,00
--------------------------------	------

No pictures to display

Roof, Scratch(es), Acceptable	0,00
-------------------------------	------

No pictures to display