



VOLKSWAGEN PASSAT VARIANT: 1KPS448

Vinnumber:	WVWZZZ3CZGE008317	Versionname:	1.6 TDI VARIANT COMFORTLINE
First Registrationdate:	11/06/2015	Fiscalpower:	
Expertise Mileage:	67258	Power Kw:	88
Bodytype:	Break	Body color:	Black
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	1125
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Sun Roof electric	
GPS storage	SD	Panoramic roof	
GPS storage		Central consol F	
Windows electric F		Luggage cover	
Windows electric R		Front parking sensors	
Cruise Control		Rear parking sensors	
Steering wheel multifunctional		Type of Tow bar	Tow bar removable
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

Summer tyres:	215/60/16/95 V LightMetal			
	Fr.L.	Continental: 4 mm	Fr.R.	Continental: 4 mm
	Re.L.	Continental: 7 mm	Re.R.	Continental: 7 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	1965,56
Wing R L, Dent(s) and scratch(es), LI - Repair and paint (complete)	308,20



Bumper F, Scratch(es), LI - Repair and paint (complete)

211,80



Rearview mirror housing R, Scratch(es), Acceptable

0,00

No pictures to display


Bonnet, Stone chip(s), Acceptable

0,00



Roof, Chemical polution, LI - Repair and paint (complete)

481,50



Door F L, Scratch(es), Acceptable

0,00

No pictures to display

Roof pillar R, Scratch(es), Acceptable

0,00

No pictures to display

Door R R, Dent(s) and scratch(es), LI - Repair and paint (complete)

318,35



Door F R, Dent(s) and scratch(es), LI - Repair and paint (complete)

318,35



Wing F L, Scratch(es), Acceptable

0,00

No pictures to display

Rearview mirror housing L, Scratch(es), LI - Repair and paint (complete)

115,56



Bumper R, Scratch(es), LI - Repair and paint (complete)

211,80



Door R L, Scratch(es), Acceptable

0,00

No pictures to display