


VOLKSWAGEN Sharan: 1FQQ736

Vinnumber:	WVWZZZ7NZE009704	Versionname:	SHARAN Trendline 140PK
First Registrationdate:	25/09/2013	Fiscalpower:	
Expertise Mileage:	122553	Power Kw:	103
Bodytype:		Body color	Black
Gearbox:	MAN 6 VIT	Paint type	Metalic
Transmission:	Front	Rims summer	Steel
Fueltype:	Diesel	Oil level	OK
Battery functioning	Yes	Parking lot	3224
Number of doors	5		
Number of seats	7		
Number head rests	7		
Rims summer	Steel		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options

Radio CD	Sun Roof electric
Windows electric F	Panoramic roof
Windows electric R	Central consol F
Steering wheel multifunctional	Luggage cover
Radio multimedia	Front parking sensors
Type of headlighting	Rear parking sensors
Type of GPS	Type of Tow bar
Type of Lining	
Type of climate control	

Headlighting Halogen
GPS big screen color
Lining fabrics
Autom climate control

No Tow bar

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

Summer tyres:	205/60/16/96 H Steel			
	Fr.L.	Michelin: 7 mm	Fr.R.	Michelin: 7 mm
	Re.L.	Continental: 7 mm	Re.R.	Continental: 7 mm

Assistance equipment

Repair kit	No	Compressor	No
------------	-----------	------------	-----------

Total cost ex VAT	912,26
Door F L, Dent(s) and scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Wing R L, Dent(s) and scratch(es), LI - Repair and paint (complete)	0,00



Mirror side blinker L, Crack, E - Replace

31,20



Bonnet, Stone chip(s), Acceptable

0,00

No pictures to display

Tailgate, Dent(s), Acceptable

0,00

No pictures to display

Wing F R, Dent(s), Acceptable

0,00

No pictures to display

Wheel cover R R, Scratch(es), E - Replace

36,00



Bumper grille, Broken, E - Replace

0,00



Bumper R, Crack, Le - Replace and paint

0,00



Rearlight L, Scratch(es), Acceptable

0,00



Foglight R, Broken, E - Replace

0,00



Wheel cover F R, Scratch(es), Acceptable

0,00

No pictures to display

Tyre repair kit, Missing, E - Replace		252,64
		
Armrest L, Incomplete, E - Replace		9,80
		
Rear spoiler, Scratch(es), Acceptable		0,00
No pictures to display		
Wheel cover R L, Scratch(es), E - Replace		36,00
		
Door F R, Scratch(es), Acceptable		0,00
No pictures to display		
Trunk lid covering R, Scratch(es), Acceptable		0,00
No pictures to display		
Seat cover F R, Stain, Cleaning		25,00
		
Door R R, Scratch(es), Acceptable		0,00
No pictures to display		
Door R L, Dent(s) and scratch(es), LI - Repair and paint (complete)		478,02
		
Internal Boot Lining R, Broken, Forfeit		24,00
		
Wing R R, Scratch(es), Acceptable		0,00
No pictures to display		
Bumper F, Crack, Le - Replace and paint		0,00
		
Reflector, Broken, E - Replace		0,00



Boot carpet, Missing, E - Replace

19,60

