



BMW 3: 1GSS460

Vinnumber:	WBA3Y11030D449639	Versionname:	3 GRAN TURISMO 318d 136PK
First Registrationdate:	1/01/2020	Fiscalpower:	
Expertise Mileage:	193247	Power Kw:	100
Bodytype:		Body color:	Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:		Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3406
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	No		

Options

Radio CD	Sun Roof electric	
Windows electric F	Panoramic roof	
Windows electric R	Central consol F	
Cruise Control	Front parking sensors	
Steering wheel multifunctional	Rear parking sensors	
Radio multimedia	Type of Tow bar	No Tow bar
Type of headlighting	Headlighting Halogen	
Type of GPS	GPS big screen color	
Type of Lining	Lining leather	
Type of climate control	Autom climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	225/55/17/97 H LightMetal			
Winter tyres:	Fr.L.	Dunlop: 4 mm	Fr.R.	Dunlop: 4 mm
	Re.L.	Dunlop: 4 mm	Re.R.	Dunlop: 4 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	1000,68
-------------------	----------------

Wing F L, Dent(s), Acceptable	0,00
-------------------------------	-------------

No pictures to display

Bonnet, Deformed / Strained, LI - Repair and paint (complete)	290,08
---	---------------



Wing R L, Scratch(es), Acceptable 0,00

No pictures to display

Wing R R, Dent(s), Acceptable 0,00

No pictures to display

Door R L, Scratch(es), Acceptable 0,00

No pictures to display


Bumper grille F L, Broken, E - Replace 32,40



Bumper R, Scratch(es), Acceptable 0,00

No pictures to display

Interior, Dirty, Cleaning 50,00



Bumper F, Deformed / Strained, Le - Replace and paint 0,00



Roof pillar R, Dent(s), PDR - Paintless dent repair 82,80





Ignition key, Missing, E - Replace 150,00



Sill outer R, Scratch(es), Acceptable 0,00

No pictures to display

Bumper grille F R, Broken, E - Replace 32,40



Registration Document, Missing, E - Replace 150,00

No pictures to display

Roof, Dent(s), PDR - Paintless dent repair 63,00



Alloy rim R L, Scratch(es), Acceptable 0,00

No pictures to display

Certificate Of Conformity, Missing, E - Replace 150,00

No pictures to display