



AUDI A4: 1KSR315			
Vinnumber:	WAUZZZ8K6FN046903	Versionname:	2.0 TDI 110KW
First Registrationdate:	24/06/2015	Fiscalpower:	
Expertise Mileage:	114492	Power Kw:	110
Bodytype:		Body color	Grey
Gearbox:	MAN 6 VIT	Paint type	Metallic
Transmission:	Front	Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Maintenance	OK	Parking lot	4719
Battery functioning	Yes		
Number of doors	4		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options			
Radio CD		Sun Roof electric	
GPS storage	DVD	Central consol F	
GPS storage		Rear parking sensors	
Windows electric F		Type of Tow bar	No Tow bar
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Seats F heated			
Radio multimedia			
Type of headlighting	Headlighting Xenon		
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		
Type of climate control	Autom climate control		
Sport seats			

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear			
Summer tyres:	245/40/18/93 Y LightMetal		
	Fr.L.	Continental: 2 mm	Fr.R.
	Re.L.	Pirelli: 8 mm	Re.R.
		Continental: 2 mm	Pirelli: 4 mm

Assistance equipment			
Emergency spare wheel	Yes	Jack	Yes
Total cost ex VAT			1178,21
Door F R, Scratch(es), Acceptable			0,00
No pictures to display			
Seat cover R L, Worn, P - Check			0,00



Bumper R, Scratch(es), Acceptable

0,00

No pictures to display

Quarter light R R, Damaged, E - Replace

138,10



Wing R L, Dent(s), Acceptable

0,00

No pictures to display

Alloy rim F L, Scratch(es), LI - Repair and paint (complete)

95,00



Alloy rim R R, Scratch(es), LI - Repair and paint (complete)

95,00



Door R R, Scratch(es), LI - Repair and paint (complete)

318,35



Alloy rim F R, Scratch(es), LI - Repair and paint (complete)

95,00



Backrest cover F L, Worn, P - Check

0,00



Sill outer R, Bad repair, P - Check

0,00



Bonnet, Bad repair, LI - Repair and paint (complete)

0,00



Wing F L, Scratch(es), Acceptable

0,00

No pictures to display

Bumper F L, Scratch(es), It - Spot repair

115,56



Bumper F R, Scratch(es), It - Spot repair

115,56



Alloy rim R L, Scratch(es), LI - Repair and paint (complete)

95,00



Door panel R R, Tear, Smart repair

110,64

