



**BMW 4 GRAN COUPE: 1LFK002**

|                                   |                          |              |                                    |
|-----------------------------------|--------------------------|--------------|------------------------------------|
| Vinnumber:                        | <b>WBA4E91070G390914</b> | Versionname: | <b>2.0 420D (120KW) GRAN COUPE</b> |
| First Registrationdate:           | <b>14/09/2015</b>        | Fiscalpower: |                                    |
| Expertise Mileage:                | <b>60218</b>             | Power Kw:    | <b>120</b>                         |
| Bodytype:                         |                          | Body color   | <b>Black</b>                       |
| Gearbox:                          | <b>MAN 6 VIT</b>         | Paint type   | <b>Metalic</b>                     |
| Transmission:                     | <b>Back</b>              | Rims summer  | <b>Aluminium</b>                   |
| Fueltype:                         | <b>Diesel</b>            | Oil level    | <b>OK</b>                          |
| Maintenance                       | <b>OK</b>                | Parking lot  | <b>2824</b>                        |
| Battery functioning               | <b>Yes</b>               |              |                                    |
| Number of doors                   | <b>5</b>                 |              |                                    |
| Number of seats                   | <b>5</b>                 |              |                                    |
| Number head rests                 | <b>4</b>                 |              |                                    |
| Rims summer                       | <b>Aluminium</b>         |              |                                    |
| Category                          | <b>Passenger Car</b>     |              |                                    |
| Oil level                         | <b>OK</b>                |              |                                    |
| Registration Certificate Car (BE) | <b>Yes</b>               |              |                                    |

**Options**

|                                |                                  |
|--------------------------------|----------------------------------|
| Radio CD                       | Central consol F                 |
| Windows electric F             | Luggage cover                    |
| Windows electric R             | Front parking sensors            |
| Cruise Control                 | Rear parking sensors             |
| Steering wheel multifunctional |                                  |
| Type of headlighting           | <b>Headlighting Xenon</b>        |
| Type of GPS                    | <b>GPS big screen color</b>      |
| Type of Lining                 | <b>Lining artificial leather</b> |
| Type of climate control        | <b>Autom climate control</b>     |

**Limited Technical Inspection**

|                     |           |                     |            |
|---------------------|-----------|---------------------|------------|
| Airco functioning   | <b>OK</b> | Battery functioning | <b>Yes</b> |
| Tires wear profile  | <b>OK</b> | Power steering      | <b>Yes</b> |
| Idle position       | <b>OK</b> | Sound engine        | <b>OK</b>  |
| Engine startingtime | <b>OK</b> | Clutch test         | <b>OK</b>  |
| Exhaust gass        | <b>OK</b> | Wiper fluid level   | <b>OK</b>  |
| Handbrake           | <b>OK</b> | Transmission        | <b>OK</b>  |
|                     |           | Lighting            | <b>OK</b>  |
|                     |           | Wiperblades         | <b>OK</b>  |

**Degree of wear**

|               |                           |                   |       |                   |
|---------------|---------------------------|-------------------|-------|-------------------|
| Summer tyres: | 225/50/17/92 H LightMetal |                   |       |                   |
|               | Fr.L.                     | Bridgestone: 4 mm | Fr.R. | Bridgestone: 4 mm |
|               | Re.L.                     | Bridgestone: 5 mm | Re.R. | Bridgestone: 5 mm |

**Assistance equipment**

|            |            |            |            |
|------------|------------|------------|------------|
| Repair kit | <b>Yes</b> | Compressor | <b>Yes</b> |
|------------|------------|------------|------------|

|                                         |               |
|-----------------------------------------|---------------|
| Total cost ex VAT                       | <b>751,20</b> |
| Alloy rim R R, Scratch(es), Acceptable  | <b>0,00</b>   |
| <i>No pictures to display</i>           |               |
| Door F L, Scratch(es), It - Spot repair | <b>115,56</b> |



Door R R, Dent(s), PDR - Paintless dent repair

63,00



Alloy rim F L, Scratch(es), Acceptable

0,00

No pictures to display

Seat cover F L, Scratch(es), Smart repair

64,32



Tailgate, Dent(s), Acceptable

0,00

No pictures to display

Alloy rim F R, Scratch(es), Acceptable

0,00

No pictures to display

Bumper F, Scratch(es), LI - Repair and paint (complete)

254,16



Bumper R, Scratch(es), LI - Repair and paint (complete)

254,16



Wing R L, Scratch(es), Acceptable

0,00

No pictures to display