



VOLKSWAGEN Sharan: 1GVG474

Vinnumber:	WVWZZZ7NZE038111	Versionname:	SHARAN Comfortline BMT 115PK
First Registrationdate:	9/05/2014	Fiscalpower:	
Expertise Mileage:	142759	Power Kw:	85
Bodytype:		Body color	Black
Gearbox:	MAN 6 VIT	Paint type	Metalic
Transmission:	Front	Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Maintenance	OK	Parking lot	3124
Battery functioning	Yes		
Number of doors	5		
Number of seats	7		
Number head rests	7		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options

Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	Front parking sensors
Cruise Control	Rear parking sensors
Steering wheel multifunctional	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining fabrics
Type of climate control	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

Summer tyres:	215/60/16/92 H LightMetal			
	Fr.L.	Continental: 4 mm	Fr.R.	Continental: 4 mm
	Re.L.	Continental: 5 mm	Re.R.	Continental: 5 mm

Assistance equipment

Total cost ex VAT	0,00
Door F R, Scratch(es), LI - Repair and paint (complete)	0,00
<i>No pictures to display</i>	
Rear bulkhead lining, Damaged, E - Replace	0,00



Tailgate, Dent(s), LI - Repair and paint (complete)

0,00



Bumper R, Scratch(es), LI - Repair and paint (complete)

0,00



Wheel hub cap R R, Missing, E - Replace

0,00



Wing R L, Scratch(es), LI - Repair and paint (complete)

0,00



Rear Panel Internal Lining, Scratch(es), E - Replace

0,00



Door R L, Scratch(es), LI - Repair and paint (complete)

0,00



Door R R, Dent(s), LI - Repair and paint (complete)

0,00



Wheel hub cap R L, Missing, E - Replace

0,00



Wing R R, Dent(s), Acceptable

0,00

No pictures to display

Wing F R, Scratch(es), Acceptable

0,00



Rocker panel inner R L, Dent(s), LI - Repair and paint (complete)

0,00

