


AUDI A5 SPORTBACK: 1TGY023

Vinnumber:	WAUZZZF56JA055193	Versionname:	2.0 TDi 110kW S tronic Bus. Ed. Design
First Registrationdate:	3/11/2017	Fiscalpower:	
Expertise Mileage:	45619	Power Kw:	110
Bodytype:		Body color	Blue
Gearbox:	Automatic	Paint type	Metallic
Transmission:	Front	Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Maintenance	OK	Parking lot	2611
Battery functioning	Yes		
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options

Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	Front parking sensors
Cruise Control	Rear parking sensors
Steering wheel multifunctional	
Seats F heated	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining leather
Type of climate control	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	245/40/18/92 H LightMetal			
Summer tyres:	Fr.L.	Bridgestone: 4 mm	Fr.R.	Bridgestone: 4 mm
	Re.L.	Bridgestone: 5 mm	Re.R.	Bridgestone: 5 mm

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
Total cost ex VAT			305,56
Door R L, Dent(s), Acceptable			0,00
<i>No pictures to display</i>			
Bumper R, Scratch(es), Acceptable			0,00
<i>No pictures to display</i>			
Bonnet, Chemical polution, Acceptable			0,00
<i>No pictures to display</i>			
Alloy rim R.D. Scratch(es), L.L. Repair and paint (complete)			05,00

Alloy rim R R, Scratch(es), LI - Repair and paint (complete)		95,00
 		
Alloy rim F R, Scratch(es), LI - Repair and paint (complete)		95,00
  		
Wing F R, Scratch(es), Acceptable		0,00
No pictures to display		
Bumper F R, Scratch(es), It - Spot repair		115,56
  		