


**BMW 3: 1GKW418**

|                                   |                          |              |                             |
|-----------------------------------|--------------------------|--------------|-----------------------------|
| Vinnumber:                        | <b>WBA3K91070F933799</b> | Versionname: | <b>3 TOURING 316d 116PK</b> |
| First Registrationdate:           | <b>6/03/2014</b>         | Fiscalpower: |                             |
| Expertise Mileage:                | <b>187154</b>            | Power Kw:    | <b>85</b>                   |
| Bodytype:                         |                          | Body color   | <b>White</b>                |
| Gearbox:                          | <b>MAN 6 VIT</b>         | Paint type   | <b>Opaque</b>               |
| Transmission:                     | <b>Back</b>              | Rims summer  | <b>Aluminium</b>            |
| Fueltype:                         | <b>Diesel</b>            | Oil level    | <b>OK</b>                   |
| Battery functioning               | <b>Yes</b>               | Parking lot  | <b>3508</b>                 |
| Number of doors                   | <b>5</b>                 |              |                             |
| Number of seats                   | <b>5</b>                 |              |                             |
| Number head rests                 | <b>5</b>                 |              |                             |
| Rims summer                       | <b>Aluminium</b>         |              |                             |
| Category                          | <b>Passenger Car</b>     |              |                             |
| Oil level                         | <b>OK</b>                |              |                             |
| Registration Certificate Car (BE) | <b>Yes</b>               |              |                             |

**Options**

|                                |                              |
|--------------------------------|------------------------------|
| Radio CD                       | Central consol F             |
| GPS storage                    | Luggage cover                |
| GPS storage                    | HD Type of Tow bar           |
| Windows electric F             | <b>No Tow bar</b>            |
| Windows electric R             |                              |
| Steering wheel multifunctional |                              |
| Radio multimedia               |                              |
| Type of headlighting           | <b>Headlighting Halogen</b>  |
| Type of GPS                    | <b>GPS big screen color</b>  |
| Type of Lining                 | <b>Lining fabrics</b>        |
| Type of climate control        | <b>Autom climate control</b> |

**Limited Technical Inspection**

|                     |           |                     |            |
|---------------------|-----------|---------------------|------------|
| Airco functioning   | <b>OK</b> | Battery functioning | <b>Yes</b> |
| Tires wear profile  | <b>OK</b> | Power steering      | <b>Yes</b> |
| Idle position       | <b>OK</b> | Sound engine        | <b>OK</b>  |
| Engine startingtime | <b>OK</b> | Clutch test         | <b>OK</b>  |
| Exhaust gass        | <b>OK</b> | Wiper fluid level   | <b>OK</b>  |
| Handbrake           | <b>OK</b> | Transmission        | <b>OK</b>  |
|                     |           | Lighting            | <b>OK</b>  |
|                     |           | Wiperblades         | <b>OK</b>  |

**Degree of wear**

|                                  |                      |                      |  |
|----------------------------------|----------------------|----------------------|--|
| <b>205/60/16/92 W LightMetal</b> |                      |                      |  |
| Summer tyres:                    | Fr.L. Michelin: 4 mm | Fr.R. Michelin: 4 mm |  |
|                                  | Re.L. Michelin: 3 mm | Re.R. Michelin: 3 mm |  |

**Assistance equipment**

|                                          |            |            |            |
|------------------------------------------|------------|------------|------------|
| Repair kit                               | <b>Yes</b> | Compressor | <b>Yes</b> |
| Number of charging cables (normal)       | <b>0</b>   |            |            |
| Number of charging cables (rapid charge) | <b>0</b>   |            |            |

|                                     |         |
|-------------------------------------|---------|
| Total cost ex VAT                   | 1436,73 |
| Door R L, Scratch(es), Acceptable   | 0,00    |
| <i>No pictures to display</i>       |         |
| Rear wiper arm, Broken, E - Replace | 40,00   |



Door F L, Scratch(es), Acceptable 0,00

No pictures to display


Alloy rim R R, Scratch(es), LI - Repair and paint (complete) 95,00




Rear spoiler, Scratch(es), 67 - Polish 0,00

No pictures to display

Roof, Chemical polution, LI - Repair and paint (complete) 481,50



Bonnet, Scratch(es), LI - Repair and paint (complete) 290,08



Bumper R, Scratch(es), Acceptable 0,00

No pictures to display

Door F R, Dent(s) and scratch(es), LI - Repair and paint (complete) 318,35



Door R R, Dent(s) and scratch(es), Acceptable 0,00

No pictures to display

Alloy rim F R, Scratch(es), Acceptable 0,00

No pictures to display

Bumper F, Scratch(es), LI - Repair and paint (complete) 211,80



|                                   |      |
|-----------------------------------|------|
| Wing R R, Scratch(es), Acceptable | 0,00 |
| No pictures to display            |      |
| Wing F L, Scratch(es), Acceptable | 0,00 |
| No pictures to display            |      |
| Wing R L, Dent(s), Acceptable     | 0,00 |
| No pictures to display            |      |