



AUDI A6 AVANT: 1LSE841

Vinnumber:	WAUZZZ4G2GN083093	Versionname:	3.0 TDI 200KW S TRONIC QUATTRO
First Registrationdate:	20/11/2015	Fiscalpower:	
Expertise Mileage:	76034	Power Kw:	200
Bodytype:		Body color:	Grey
Gearbox:	Automatic	Paint type:	Metalic
Transmission:	4 Wheel	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	1106
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Seats electric F L
Windows electric F	Seats electric F R
Windows electric R	Central consol F
Steering wheel multifunctional	Luggage cover
Seats F heated	Front parking sensors
Radio multimedia	Rear parking sensors
Type of headlighting	Type of Tow bar
Type of GPS	Headlighting Xenon
Type of Lining	GPS big screen color
Type of climate control	Lining leather
	Autom climate control
	Tow bar fixed

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

245/45/18/100 Y LightMetal			
Summer tyres:	Fr.L.	Continental: 5 mm	Fr.R.
	Re.L.	Continental: 5 mm	Re.R.
		Continental: 5 mm	

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	444,16
Alloy rim F L, Scratch(es), Acceptable	0,00
No pictures to display	
Wing R R, Scratch(es), Acceptable	0,00
No pictures to display	
Rearview mirror housing R, Scratch(es), Acceptable	0,00
No pictures to display	

no pictures to display

Alloy rim F R, Scratch(es), LI - Repair and paint (complete)	95,00
--	-------



Alloy rim R R, Scratch(es), LI - Repair and paint (complete)	95,00
--	-------



Bumper R, Scratch(es), LI - Repair and paint (complete)	254,16
---	--------

