



VOLVO V70: 1KTR962

Vinnumber:	YV1BW31A1D1273713	Versionname:	
First Registrationdate:	2/05/2013	Fiscalpower:	
Expertise Mileage:	232805	Power Kw:	100
Bodytype:		Body color	Silver
Gearbox:	MAN 6 VIT	Paint type	Metalic
Transmission:	Front	Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Maintenance	OK	Parking lot	4128
Battery functioning	Yes		
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options

Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	Rear parking sensors
Cruise Control	Type of Tow bar
Steering wheel multifunctional	Tow bar fixed
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining artificial leather
Type of climate control	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

Summer tyres:	225/55/16/92 H LightMetal			
	Fr.L.	Hankook: 5 mm	Fr.R.	Hankook: 5 mm
	Re.L.	Hankook: 6 mm	Re.R.	Hankook: 6 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	348,00
-------------------	---------------

Wing R L, Dent(s), PDR - Paintless dent repair	63,00
--	--------------



Alloy rim F L, Scratch(es), LI - Repair and paint (complete)		95,00
		
Alloy rim F R, Scratch(es), LI - Repair and paint (complete)		95,00
		
Bumper F, Scratch(es), Acceptable		0,00
No pictures to display		
Alloy rim R R, Scratch(es), LI - Repair and paint (complete)		95,00
		
Bumper R, Scratch(es), Acceptable		0,00
No pictures to display		