


AUDI A6 AVANT: 1NHH929

Vinnumber:	WAUZZZ4G4GN148705	Versionname:	2.0 TDI ULTRA 140KW S TRONIC
First Registrationdate:	25/02/2016	Fiscalpower:	
Expertise Mileage:	111280	Power Kw:	140
Bodytype:		Body color	Black
Gearbox:	Automatic	Paint type	Metalic
Transmission:	Front	Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Battery functioning	Yes	Parking lot	1333
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options

Radio CD		Central consol F	
GPS storage	HD	Luggage cover	
GPS storage		Front parking sensors	
Windows electric F		Rear parking sensors	
Windows electric R		Type of Tow bar	No Tow bar
Cruise Control			
Steering wheel multifunctional			
Seats F heated			
Radio multimedia			
Type of headlighting	Headlighting Xenon		
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	225/55/17/97 H LightMetal			
Winter tyres:	Fr.L.	Michelin: 7 mm	Fr.R.	Michelin: 7 mm
	Re.L.	Michelin: 6 mm	Re.R.	Michelin: 6 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT		4141,83
Bonnet, Chemical polution, LI - Repair and paint (complete)		348,09



Alloy rim F R, Scratch(es), LI - Repair and paint (complete)

95,00



Wing R L, Scratch(es), Acceptable

0,00

No pictures to display

Rearview mirror housing R, Scratch(es), Acceptable

0,00

No pictures to display

Switch window control F L, Broken, E - Replace

38,50




Sill outer R, Scratch(es), LI - Repair and paint (complete)

372,60



Rear window, Scratch(es), E - Replace

0,00



Rear spoiler, Scratch(es), Acceptable

0,00

No pictures to display

Wing F R, Scratch(es), Acceptable

0,00

No pictures to display

Alloy rim R R, Scratch(es), LI - Repair and paint (complete)

95,00



Door R L, Scratch(es), LI - Repair and paint (complete)

382,02



Door F R, Scratch(es), Acceptable

0,00

No pictures to display

Bumper F, Deformed / Strained, Le - Replace and paint

862,80



Bumper R, Dent(s) and scratch(es), LI - Repair and paint (complete)

254,16



Wing R R, Scratch(es), LI - Repair and paint (complete)

369,84



Ignition key, Missing, E - Replace	150,00
------------------------------------	--------

No pictures to display

Alloy rim R L, Scratch(es), LI - Repair and paint (complete)	95,00
--	-------



Wing F L, Deformed / Strained, Forfeit	24,00
--	-------




Door F L, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Alloy rim F L, Scratch(es), LI - Repair and paint (complete)	95,00
--	-------



Roof, Chemical polution, LI - Repair and paint (complete)	577,80
---	--------



Door R R, Dent(s) and scratch(es), LI - Repair and paint (complete)	382,02
---	--------



Tailgate, Scratch(es), Acceptable

0,00

No pictures to display