



AUDI A4: 1GMG313				
Vinnumber:	WAUZZZ8K0EA119494	Versionname:	A4 AVANT TDi 120PK	
First Registrationdate:	10/03/2014	Fiscalpower:		
Expertise Mileage:	174771	Power Kw:	88	
Bodytype:		Body color	Grey	
Gearbox:	MAN 6 VIT	Paint type	Metalic	
Transmission:	Front	Rims summer	Aluminium	
Fueltype:	Diesel	Oil level	OK	
Maintenance	7100	Parking lot	2632	
Maintenance	480 DAGEN			
Maintenance	OK			
Battery functioning	Yes			
Number of doors	5			
Number of seats	5			
Number head rests	5			
Rims summer	Aluminium			
Category	Passenger Car			
Oil level	OK			
Registration Certificate Car (BE)	Yes			
Options				
Radio CD		Central consol F		
GPS storage		Luggage cover		
GPS storage	CD	Rear parking sensors		
Windows electric F		Type of Tow bar	No Tow bar	
Windows electric R				
Cruise Control				
Steering wheel multifunctional				
Type of headlighting	Headlighting Halogen			
Type of GPS	GPS big screen color			
Type of Lining	Lining fabrics			
Type of climate control	Autom climate control			
Limited Technical Inspection				
Airco functioning	OK	Battery functioning	Yes	
Tires wear profile	OK	Power steering	Yes	
Idle position	OK	Sound engine	OK	
Engine startingtime	OK	Clutch test	OK	
Exhaust gass	OK	Wiper fluid level	OK	
Handbrake	OK	Transmission	OK	
		Lighting	OK	
		Wiperblades	OK	
Degree of wear				
Summer tyres:	225/55/16/95 Y LightMetal			
	Fr.L.	Michelin: 5 mm	Fr.R.	Michelin: 5 mm
	Re.L.	Michelin: 3 mm	Re.R.	Michelin: 3 mm
Assistance equipment				
Emergency spare wheel	Yes	Jack	Yes	
Total cost ex VAT			291,80	
Mirror side blinker R, Broken, E - Replace			30,00	



Door R R, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Seat cover F R, Stain, Cleaning	25,00
---------------------------------	-------



Bumper R, Scratch(es), LI - Repair and paint (complete)	211,80
---	--------



Bumper F, Repaired, Acceptable	0,00
--------------------------------	------

No pictures to display

Windscreen, Stone chip(s), Windscreen repair	0,00
--	------



Rearview mirror housing R, Scratch(es), Acceptable	0,00
--	------

No pictures to display

MOT Certificate, Missing, Acceptable	0,00
--------------------------------------	------



Internal Boot Lining L, Scratch(es), Acceptable	0,00
---	------

No pictures to display

Backrest cover F L, Stain, Cleaning	25,00
-------------------------------------	-------



Wing R L, Dent(s), Acceptable	0,00
-------------------------------	------

No pictures to display

Outer backrest protection L, Scratch(es), Acceptable	0,00
--	------

No pictures to display

Outer backrest protection R, Scratch(es), Acceptable	0,00
--	------

No pictures to display

Bumper F, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Wing R R, Dent(s) and scratch(es), Acceptable	0,00
---	------

No pictures to display