


FORD TRANSIT COURIER: 1TJK551

Vinnumber:	WF0WXXTACWHK44771	Versionname:	1.5 TDCi 56kW Trend
First Registrationdate:	17/11/2017	Fiscalpower:	
Expertise Mileage:	180500	Power Kw:	56
Bodytype:	Transporter	Body color:	White
Gearbox:	MAN 5 VIT	Paint type:	Opaque
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	NOT OK
Battery functioning:	Yes	Parking lot:	PARKING VOORAAN
Number of doors:	5		
Number of seats:	2		
Number head rests:	2		
Rims summer:	Steel		
Category:	Light Commercial Vehicle		
Oil level:	NOT OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Rear parking sensors
Windows electric F	
Radio multimedia	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining fabrics
Type of climate control	Manual climate control

Limited Technical Inspection

Tires wear profile	OK	Battery functioning	Yes
Idle position	NOT OK	Power steering	Yes
Engine startingtime	NOT OK	Sound engine	NOT OK
Exhaust gass	NOT OK	Clutch test	OK
Handbrake	OK	Wiper fluid level	OK
		Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

Summer tyres:	195/60/15/88 V Steel			
	Fr.L.	BF Goodrich: 5 mm	Fr.R.	BF Goodrich: 5 mm
	Re.L.	BF Goodrich: 4 mm	Re.R.	BF Goodrich: 4 mm

Assistance equipment

Spare wheel	No
Emergency spare wheel	No
Repair kit	No

Total cost ex VAT	1700,06
Windscreen, Stone chip(s), E - Replace	395,40



Wheel cover F R, Missing, E - Replace

22,50



Spare Tyre, Deformed / Strained, E - Replace

105,00



Wheel cover R R, Missing, E - Replace

22,50



Bumper R, Deformed / Strained, E - Replace

329,40



Engine, Not functioning (well), P - Check

0,00



Gear shift lever knob, Broken, E - Replace

91,50



Ignition key, Missing, E - Replace

150,00

No pictures to display

Bodywork, Not original part, Remove lettering

0,00

No pictures to display

Rearview mirror housing L, Scratch(es), Acceptable

0,00

No pictures to display

Door F L, Scratch(es), LI - Repair and paint (complete)

238,76



Backrest cover F L, Tear, E - Replace

300,00



Bumper F, Scratch(es), Acceptable

0,00

No pictures to display

Wheel cover R L, Missing, E - Replace

22,50



Door F R, Dent(s), Acceptable

0,00

No pictures to display

Wheel covers F L, Missing, E - Replace

22,50

