



**AUDI A6: 1HSR515**

|                                   |                          |              |                       |
|-----------------------------------|--------------------------|--------------|-----------------------|
| Vinnumber:                        | <b>WAUZZZ4G9EN168767</b> | Versionname: | <b>A6 AVANT 136PK</b> |
| First Registrationdate:           | <b>1/01/2020</b>         | Fiscalpower: |                       |
| Expertise Mileage:                | <b>166870</b>            | Power Kw:    | <b>100</b>            |
| Bodytype:                         |                          | Body color   | <b>Grey</b>           |
| Gearbox:                          | <b>MAN 6 VIT</b>         | Paint type   | <b>Metallic</b>       |
| Transmission:                     | <b>Front</b>             | Rims summer  | <b>Aluminium</b>      |
| Fueltype:                         | <b>Diesel</b>            | Oil level    | <b>OK</b>             |
| Battery functioning               | <b>Yes</b>               | Parking lot  | <b>2809</b>           |
| Number of doors                   | <b>5</b>                 |              |                       |
| Number of seats                   | <b>5</b>                 |              |                       |
| Number head rests                 | <b>5</b>                 |              |                       |
| Rims summer                       | <b>Aluminium</b>         |              |                       |
| Category                          | <b>Passenger Car</b>     |              |                       |
| Oil level                         | <b>OK</b>                |              |                       |
| Registration Certificate Car (BE) | <b>No</b>                |              |                       |

**Options**

|                                |                              |
|--------------------------------|------------------------------|
| Radio CD                       | Central consol F             |
| Windows electric F             | Luggage cover                |
| Windows electric R             | Front parking sensors        |
| Cruise Control                 | Rear parking sensors         |
| Steering wheel multifunctional | Type of Tow bar              |
| Seats F heated                 | <b>No Tow bar</b>            |
| Radio multimedia               |                              |
| Type of headlighting           | <b>Headlighting Xenon</b>    |
| Type of GPS                    | <b>GPS big screen color</b>  |
| Type of Lining                 | <b>Lining leather</b>        |
| Type of climate control        | <b>Autom climate control</b> |

**Limited Technical Inspection**

|                     |           |                     |            |
|---------------------|-----------|---------------------|------------|
| Airco functioning   | <b>OK</b> | Battery functioning | <b>Yes</b> |
| Tires wear profile  | <b>OK</b> | Power steering      | <b>Yes</b> |
| Idle position       | <b>OK</b> | Sound engine        | <b>OK</b>  |
| Engine startingtime | <b>OK</b> | Clutch test         | <b>OK</b>  |
| Exhaust gass        | <b>OK</b> | Wiper fluid level   | <b>OK</b>  |
| Handbrake           | <b>OK</b> | Transmission        | <b>OK</b>  |
|                     |           | Lighting            | <b>OK</b>  |
|                     |           | Wiperblades         | <b>OK</b>  |

**Degree of wear**

|               |                           |                   |       |                   |
|---------------|---------------------------|-------------------|-------|-------------------|
| Summer tyres: | 225/55/17/97 V LightMetal |                   |       |                   |
|               | Fr.L.                     | Continental: 3 mm | Fr.R. | Continental: 3 mm |
|               | Re.L.                     | Continental: 5 mm | Re.R. | Continental: 5 mm |

**Assistance equipment**

|                                          |            |      |            |
|------------------------------------------|------------|------|------------|
| Emergency spare wheel                    | <b>Yes</b> | Jack | <b>Yes</b> |
| Number of charging cables (normal)       | <b>0</b>   |      |            |
| Number of charging cables (rapid charge) | <b>0</b>   |      |            |

|                                                         |         |
|---------------------------------------------------------|---------|
| Total cost ex VAT                                       | 1158,37 |
| Ignition key, Missing, E - Replace                      | 150,00  |
| <i>No pictures to display</i>                           |         |
| Bumper F, Scratch(es), LI - Repair and paint (complete) | 254,16  |



Rear window, Scratch(es), E - Replace

0,00



Registration Document, Missing, E - Replace

150,00

*No pictures to display*

Wing F L, Dent(s), LI - Repair and paint (complete)

264,21



Certificate Of Conformity, Missing, E - Replace

150,00

*No pictures to display*

Alloy rim F L, Scratch(es), LI - Repair and paint (complete)

95,00



Wing F R, Scratch(es), Acceptable

0,00

*No pictures to display*

Bumper R, Scratch(es), Acceptable

0,00

*No pictures to display*

Door F L, Scratch(es), Acceptable

0,00

*No pictures to display*

Alloy rim F R, Scratch(es), LI - Repair and paint (complete)

95,00

