


**AUDI A6: GG6998**

|                                   |                          |              |                                    |
|-----------------------------------|--------------------------|--------------|------------------------------------|
| Vinnumber:                        | <b>WAUZZZ4G0EN146236</b> | Versionname: | <b>A6 AVANT Multitr.177PK Aut.</b> |
| First Registrationdate:           | <b>27/05/2014</b>        | Fiscalpower: |                                    |
| Expertise Mileage:                | <b>116674</b>            | Power Kw:    | <b>130</b>                         |
| Bodytype:                         |                          | Body color   | <b>Black</b>                       |
| Gearbox:                          | <b>Automatic</b>         | Paint type   | <b>Metallic</b>                    |
| Transmission:                     | <b>Back</b>              | Rims summer  | <b>Aluminium</b>                   |
| Fueltype:                         | <b>Diesel</b>            | Oil level    | <b>OK</b>                          |
| Maintenance                       | <b>OK</b>                | Parking lot  | <b>2229</b>                        |
| Battery functioning               | <b>Yes</b>               |              |                                    |
| Number of doors                   | <b>5</b>                 |              |                                    |
| Number of seats                   | <b>5</b>                 |              |                                    |
| Number head rests                 | <b>5</b>                 |              |                                    |
| Rims summer                       | <b>Aluminium</b>         |              |                                    |
| Category                          | <b>Passenger Car</b>     |              |                                    |
| Oil level                         | <b>OK</b>                |              |                                    |
| Registration Certificate Car (BE) | <b>Yes</b>               |              |                                    |

**Options**

|                                |                                     |
|--------------------------------|-------------------------------------|
| Radio CD                       | Central consol F                    |
| Windows electric F             | Luggage cover                       |
| Windows electric R             | Front parking sensors               |
| Cruise Control                 | Rear parking sensors                |
| Steering wheel multifunctional |                                     |
| Seats F heated                 |                                     |
| Type of headlighting           | <b>Headlighting Halogen</b>         |
| Type of GPS                    | <b>GPS big screen color</b>         |
| Type of Lining                 | <b>Lining leather and alcantara</b> |
| Type of climate control        | <b>Autom climate control</b>        |

**Limited Technical Inspection**

|                     |           |                     |            |
|---------------------|-----------|---------------------|------------|
| Airco functioning   | <b>OK</b> | Battery functioning | <b>Yes</b> |
| Tires wear profile  | <b>OK</b> | Power steering      | <b>Yes</b> |
| Idle position       | <b>OK</b> | Sound engine        | <b>OK</b>  |
| Engine startingtime | <b>OK</b> | Clutch test         | <b>OK</b>  |
| Exhaust gass        | <b>OK</b> | Wiper fluid level   | <b>OK</b>  |
| Handbrake           | <b>OK</b> | Transmission        | <b>OK</b>  |
|                     |           | Lighting            | <b>OK</b>  |
|                     |           | Wiperblades         | <b>OK</b>  |

**Degree of wear**

|               |                           |                   |       |                   |
|---------------|---------------------------|-------------------|-------|-------------------|
| Summer tyres: | 245/45/18/92 H LightMetal |                   |       |                   |
|               | Fr.L.                     | Bridgestone: 4 mm | Fr.R. | Bridgestone: 4 mm |
|               | Re.L.                     | Bridgestone: 5 mm | Re.R. | Bridgestone: 5 mm |

**Assistance equipment**

|                                                         |            |      |               |
|---------------------------------------------------------|------------|------|---------------|
| Emergency spare wheel                                   | <b>Yes</b> | Jack | <b>Yes</b>    |
| Total cost ex VAT                                       |            |      | <b>746,32</b> |
| Alloy rim F L, Scratch(es), Acceptable                  |            |      | <b>0,00</b>   |
| <i>No pictures to display</i>                           |            |      |               |
| Bumper F, Scratch(es), LI - Repair and paint (complete) |            |      | <b>254,16</b> |



|                               |      |
|-------------------------------|------|
| Wing R L, Dent(s), Acceptable | 0,00 |
|-------------------------------|------|

No pictures to display

|                                                              |       |
|--------------------------------------------------------------|-------|
| Alloy rim R L, Scratch(es), LI - Repair and paint (complete) | 95,00 |
|--------------------------------------------------------------|-------|



|                                       |      |
|---------------------------------------|------|
| Bonnet, Chemical polution, Acceptable | 0,00 |
|---------------------------------------|------|

No pictures to display

|                                                              |       |
|--------------------------------------------------------------|-------|
| Alloy rim F R, Scratch(es), LI - Repair and paint (complete) | 95,00 |
|--------------------------------------------------------------|-------|



|                           |      |
|---------------------------|------|
| Interior, Dirty, Cleaning | 0,00 |
|---------------------------|------|



|                                                         |        |
|---------------------------------------------------------|--------|
| Bumper R, Scratch(es), LI - Repair and paint (complete) | 302,16 |
|---------------------------------------------------------|--------|



|                                        |      |
|----------------------------------------|------|
| Alloy rim R R, Scratch(es), Acceptable | 0,00 |
|----------------------------------------|------|

No pictures to display