



RENAULT Scenic: 1HUB020

Vinnumber:	VF1JZ14K651527649	Versionname:	SCENIC Energy Zen 110PK
First Registrationdate:	2/10/2014	Fiscalpower:	
Expertise Mileage:	80923	Power Kw:	81
Bodytype:		Body color	Grey
Gearbox:	MAN 6 VIT	Paint type	Metalic
Transmission:	Front	Rims summer	Steel
Fueltype:	Diesel	Oil level	OK
Battery functioning	Yes	Parking lot	2401
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Steel		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options

Radio CD	Sun Roof electric
Windows electric F	Panoramic roof
Windows electric R	Central consol F
Cruise Control	Luggage cover
Steering wheel multifunctional	Front parking sensors
Radio multimedia	Rear parking sensors
Type of headlighting	Type of Tow bar
Type of GPS	Headlighting Halogen
Type of Lining	GPS big screen color
Type of climate control	Lining semi-artificial leather
	Autom climate control
	Tow bar fixed

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

205/60/16/92 H Steel			
Summer tyres:	Fr.L.	Michelin: 4 mm	Fr.R.
	Re.L.	Michelin: 4 mm	Re.R.
		Michelin: 4 mm	

Assistance equipment

Spare wheel	Yes	Jack	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	659,88
Bumper R, Scratch(es), Acceptable	0,00
No pictures to display	
Door F R, Scratch(es), Acceptable	0,00
No pictures to display	
Bonnet, Chemical polution, LI - Repair and paint (complete)	290,08



Rear window, Scratch(es), Acceptable	0,00
--------------------------------------	------

No pictures to display

Door F L, Dent(s) and scratch(es), Acceptable	0,00
---	------

No pictures to display

Alloy rim F R, Scratch(es), Acceptable	0,00
--	------

No pictures to display

Wing R R, Dent(s), PDR - Paintless dent repair	63,00
--	-------



Bumper F, Scratch(es), LI - Repair and paint (complete)	211,80
---	--------



Alloy rim F L, Scratch(es), LI - Repair and paint (complete)	95,00
--	-------

