Print

VOLKSWAGEN GOLF VII: 1LBY962

Vinnumber:	WVWZZZAUZGW049934	Versionname:	1.6 TDI 81KW HIGHLINE
First Registrationdate:	14/08/2015	Fiscalpower:	
Expertise Mileage:	179553	Power Kw:	81
Bodytype:		Body color	Black
Gearbox:	MAN 5 VIT	Paint type	Metalic
Transmission:	Front	Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Battery functioning	Yes	Parking lot	2722
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options

Radio CD		Sun Roof electric	
GPS storage		Central consol F	
GPS storage	SD	Luggage cover	
Windows electric F		Front parking sensors	
Windows electric R		Rear parking sensors	
Cruise Control		Type of Tow bar	Tow bar fixed
Steering wheel multifunctional			
Seats F heated			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining semi-Alcantara		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

Summer tyres:	205/55/16/91 V LightMetal			
	Fr.L.	Michelin: 5 mm	Fr.R.	Michelin: 5 mm
	Re.L.	Michelin: 5 mm	Re.R.	Michelin: 5 mm

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	520,00
Wing R L, Scratch(es), Acceptable	0,00

No pictures to display

Tailgate, Dent(s), Acceptable	0,00

No pictures to display

Door R R, Dent(s), Acceptable	0,00

No pictures to display

Backrest cover F L, Worn, Acceptable	0,00

Roof, Scratch(es), Acceptable	0,00

No pictures to display

Wing F L, Dent(s), Acceptable	0,00

No pictures to display

Door R L, Dent(s) and scratch(es), Acceptable	0,00

No pictures to display

Bumper F, Scratch(es), Acceptable	0,00

No pictures to display

Door F L, Scratch(es), Acceptable	0,00

No pictures to display

Wing F R, Scratch(es), Acceptable	0,00

No pictures to display

Bumper R, Scratch(es), LI - Repair and paint (complete)	211,80

Wing R R, Dent(s) and scratch(es), LI - Repair and paint (complete)	308,20



Ignition key, Missing, E - Replace	0,00

No pictures to display