


**HYUNDAI ix35: 1HDC681**

|                                   |                          |              |                                 |
|-----------------------------------|--------------------------|--------------|---------------------------------|
| Vinnumber:                        | <b>TMAJU81VCEJ596827</b> | Versionname: | <b>ix35 4WD Executive 136PK</b> |
| First Registrationdate:           | <b>23/06/2014</b>        | Fiscalpower: |                                 |
| Expertise Mileage:                | <b>149348</b>            | Power Kw:    | <b>100</b>                      |
| Bodytype:                         |                          | Body color   | <b>Black</b>                    |
| Gearbox:                          | <b>MAN 6 VIT</b>         | Paint type   | <b>Metalic</b>                  |
| Transmission:                     | <b>4 Weel</b>            | Rims summer  | <b>Aluminium</b>                |
| Fueltype:                         | <b>Diesel</b>            | Oil level    | <b>OK</b>                       |
| Battery functioning               | <b>Yes</b>               | Parking lot  | <b>1110</b>                     |
| Number of doors                   | <b>5</b>                 |              |                                 |
| Number of seats                   | <b>5</b>                 |              |                                 |
| Number head rests                 | <b>5</b>                 |              |                                 |
| Rims summer                       | <b>Aluminium</b>         |              |                                 |
| Category                          | <b>Passenger Car</b>     |              |                                 |
| Oil level                         | <b>OK</b>                |              |                                 |
| Registration Certificate Car (BE) | <b>Yes</b>               |              |                                 |

**Options**

|                                |                                  |
|--------------------------------|----------------------------------|
| Radio CD                       | Central consol F                 |
| Windows electric F             | Luggage cover                    |
| Windows electric R             | Front parking sensors            |
| Cruise Control                 | Rear parking sensors             |
| Steering wheel multifunctional | Type of Tow bar                  |
| Seats F heated                 | <b>Tow bar removable</b>         |
| Radio multimedia               |                                  |
| Type of headlighting           | <b>Headlighting Xenon</b>        |
| Type of GPS                    | <b>GPS big screen color</b>      |
| Type of Lining                 | <b>Lining artificial leather</b> |
| Type of climate control        | <b>Autom climate control</b>     |

**Limited Technical Inspection**

|                     |           |                     |            |
|---------------------|-----------|---------------------|------------|
| Airco functioning   | <b>OK</b> | Battery functioning | <b>Yes</b> |
| Tires wear profile  | <b>OK</b> | Power steering      | <b>Yes</b> |
| Idle position       | <b>OK</b> | Sound engine        | <b>OK</b>  |
| Engine startingtime | <b>OK</b> | Clutch test         | <b>OK</b>  |
| Exhaust gass        | <b>OK</b> | Wiper fluid level   | <b>OK</b>  |
| Handbrake           | <b>OK</b> | Transmission        | <b>OK</b>  |
|                     |           | Lighting            | <b>OK</b>  |
|                     |           | Wiperblades         | <b>OK</b>  |

**Degree of wear**

|               |                           |               |       |               |
|---------------|---------------------------|---------------|-------|---------------|
| Summer tyres: | 225/55/18/98 H LightMetal |               |       |               |
|               | Fr.L.                     | Hankook: 4 mm | Fr.R. | Hankook: 4 mm |
|               | Re.L.                     | Hankook: 4 mm | Re.R. | Hankook: 4 mm |

**Assistance equipment**

|                                          |            |      |            |
|------------------------------------------|------------|------|------------|
| Spare wheel                              | <b>Yes</b> | Jack | <b>Yes</b> |
| Number of charging cables (normal)       | <b>0</b>   |      |            |
| Number of charging cables (rapid charge) | <b>0</b>   |      |            |

|                                                         |                |
|---------------------------------------------------------|----------------|
| Total cost ex VAT                                       | <b>1088,53</b> |
| Door F L, Scratch(es), LI - Repair and paint (complete) | <b>318,35</b>  |



Mirror side blinker R, Broken, E - Replace

30,00



Wing R L, Bad repair, Acceptable

0,00

No pictures to display

Wing F L, Scratch(es), Acceptable

0,00

No pictures to display

Seat cover F L, Worn, Acceptable

0,00



Bumper F, Scratch(es), Acceptable

0,00

No pictures to display

Wing R L, Dent(s), Acceptable

0,00

No pictures to display

Wing F R, Dent(s), LI - Repair and paint (complete)

220,18



Wing R R, Dent(s) and scratch(es), LI - Repair and paint (complete)

308,20



Bumper R, Scratch(es), LI - Repair and paint (complete)

211,80

