



LU AUDI a3 Limousine: UK8801

Vinnumber:	WAUZZZ8V8J1029286	Versionname:	1.0 TFSI 85kW
First Registrationdate:	22/11/2017	Fiscalpower:	
Expertise Mileage:	12218	Power Kw:	85
Bodytype:		Body color	Blue
Gearbox:	MAN 6 VIT	Paint type	Metalic
Transmission:	Front	Rims summer	Aluminium
Fueltype:	Petrol	Oil level	OK
Maintenance	OK	Parking lot	1713
Maintenance	DANS 17900 KMS OU 30 JOURS		
Battery functioning	Yes		
Number of doors	4		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options

Radio CD	Central consol F
GPS storage	SD
GPS storage	Rear parking sensors
Windows electric F	Type of Tow bar
Windows electric R	No Tow bar
Cruise Control	
Steering wheel multifunctional	
Alarm	
Radio multimedia	
Type of headlighting	Headlighting Xenon
Type of GPS	GPS big screen color
Type of Lining	Lining fabrics
Type of climate control	Autom climate control
Level control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

205/55/16/91 H LightMetal			
Winter tyres:	Fr.L.	Michelin: 7 mm	Fr.R.
	Re.L.	Michelin: 7 mm	Re.R.

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
Total cost ex VAT			306,80
Alloy rim F R, Scratch(es), LI - Repair and paint (complete)			95,00



Bonnet, Stone chip(s), Acceptable	0,00
No pictures to display	
Bumper F, Scratch(es), Acceptable	0,00
No pictures to display	
Alloy rim R L, Scratch(es), Acceptable	0,00
No pictures to display	
Door R R, Dent(s), Acceptable	0,00
No pictures to display	
Alloy rim R R, Scratch(es), Acceptable	0,00
No pictures to display	
Bumper R, Scratch(es), LI - Repair and paint (complete)	211,80

