



RENAULT Clio: 1JAG493

Vinnumber:	VF15RTL0E51807565	Versionname:	CLIO IV BER Expression EDC 90PK Aut.
First Registrationdate:	15/11/2014	Fiscalpower:	
Expertise Mileage:	61789	Power Kw:	66
Bodytype:		Body color	Red
Gearbox:	Automatic	Paint type	Metalic
Transmission:	Front	Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Battery functioning	Yes	Parking lot	3733
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options

Windows electric F	Luggage cover
Cruise Control	Rear parking sensors
Steering wheel multifunctional	Type of Tow bar
Radio multimedia	Tow bar removable
Type of headlighting	Headlighting Halogen
Type of GPS	No GPS
Type of Lining	Lining fabrics
Type of climate control	Manual climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	NOT OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	195/55/16/87 H LightMetal			
Summer tyres:	Fr.L.	Continental: 4 mm	Fr.R.	Continental: 4 mm
	Re.L.	Continental: 4 mm	Re.R.	Continental: 4 mm

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	1504,44
Wing R R, Dent(s) and scratch(es), LI - Repair and paint (complete)	294,56



Door R R, Scratch(es), LI - Repair and paint (complete)	254,68
	
Bumper R, Scratch(es), LI - Repair and paint (complete)	169,44
	
Alloy rim R R, Scratch(es), LI - Repair and paint (complete)	95,00
	
Alloy rim F L, Scratch(es), LI - Repair and paint (complete)	95,00
	
Door F L, Scratch(es), Acceptable	0,00
No pictures to display	
Roof, Scratch(es), LI - Repair and paint (complete)	385,20
	
Rearview mirror housing R, Scratch(es), LI - Repair and paint (complete)	115,56
	
Bumper F, Scratch(es), Acceptable	0,00
No pictures to display	
Alloy rim F R, Scratch(es), LI - Repair and paint (complete)	95,00
	
Wing F R, Scratch(es), Acceptable	0,00
No pictures to display	