



RENAULT CLIO: 1LXF447

Vinnumber:	VF15R0J0A54033971	Versionname:	1.5 ENERGY DCI 90E EXPRESSION
First Registrationdate:	22/12/2015	Fiscalpower:	
Expertise Mileage:	97761	Power Kw:	66
Bodytype:		Body color	Silver
Gearbox:	MAN 5 VIT	Paint type	Metalic
Transmission:	Front	Rims summer	Steel
Fueltype:	Diesel	Oil level	OK
Battery functioning	Yes	Parking lot	1433
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Steel		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options

GPS storage		Luggage cover	
GPS storage	HD	Type of Tow bar	No Tow bar
Windows electric F			
Cruise Control			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Manual climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	185/65/15/92 T Steel			
Summer tyres:	Fr.L.	Uniroyal: 4 mm	Fr.R.	Uniroyal: 4 mm
	Re.L.	Bridgestone: 5 mm	Re.R.	Bridgestone: 5 mm

Assistance equipment


Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	1206,32
Wheel cover F L, Scratch(es), E - Replace	24,00



Windscreen, Scratch(es), E - Replace

413,76




Door F L, Dent(s) and scratch(es), Acceptable

0,00

No pictures to display

Rear window, Scratch(es), E - Replace

320,00



Wheel cover F R, Scratch(es), Acceptable

0,00

No pictures to display

Wheel cover R R, Scratch(es), E - Replace

24,00



Wing R R, Scratch(es), Acceptable

0,00

No pictures to display

Wing R L, Scratch(es), 67 - Polish

0,00

No pictures to display

Wheel cover R L, Scratch(es), E - Replace

24,00





Rocker panel inner R R, Dent(s), LI - Repair and paint (complete)

115,56



Door R R, Scratch(es), Acceptable

0,00

No pictures to display

Rocker panel inner R L, Dent(s), LI - Repair and paint (complete)

115,56



Door R L, Scratch(es), Acceptable

0,00

No pictures to display

Bumper R, Dent(s) and scratch(es), LI - Repair and paint (complete)

169,44

