


BMW 4 GRAN COUPE: 1KVU504

Vinnumber:	WBA4D51020D425193	Versionname:	2.0 418D (100KW) GRAN COUPE
First Registrationdate:	16/07/2015	Fiscalpower:	
Expertise Mileage:	99895	Power Kw:	100
Bodytype:		Body color	Black
Gearbox:	MAN 6 VIT	Paint type	Metalic
Transmission:	Back	Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Maintenance	OK	Parking lot	4129
Battery functioning	Yes		
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options

Radio CD	Central consol F
GPS storage	Luggage cover
GPS storage	HD Front parking sensors
Windows electric F	Rear parking sensors
Windows electric R	Type of Tow bar
Cruise Control	No Tow bar
Steering wheel multifunctional	
Radio multimedia	
Type of headlighting	Headlighting LED
Type of GPS	GPS big screen color
Type of Lining	Lining leather
Type of climate control	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	225/50/17/94 W LightMetal			
Summer tyres:	Fr.L.	Hankook: 5 mm	Fr.R.	Hankook: 5 mm
	Re.L.	Hankook: 4 mm	Re.R.	Hankook: 4 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	598,44
Door R L, Dent(s), PDR - Paintless dent repair	63,00



Wing R L, Dent(s), LI - Repair and paint (complete)	369,84
---	--------



Door F R, Dent(s), PDR - Paintless dent repair	102,60
--	--------



Door frame R L, Scratch(es), Acceptable	0,00
---	------

No pictures to display

Door F L, Dent(s), PDR - Paintless dent repair	63,00
--	-------



Bumper F L, Scratch(es), Acceptable	0,00
-------------------------------------	------

No pictures to display