













				NIT.	ALCRE	070
А	וטט	A4	AVE	AIN I:	1KNL	.019

Vinnumber: WAUZZZ8K5FA129357 First Registrationdate: 3/06/2015 Expertise Mileage: 123315 Bodytype: Gearbox: Automatic Transmission: Front Fueltype: Diesel Maintenance ок Battery functioning Yes Number of doors 5 Number of seats 5 Number head rests Rims summer **Aluminium** Category Passenger Car Oil level ок Registration Certificate Car (BE)

2.0 TDI 110KW MULTITRONIC Versionname:

Fiscalpower: Power Kw:

Body color Paint type Rims summer Oil level Parking lot

Options

Radio CD GPS storage GPS storage Windows electric F Windows electric R Cruise Control Steering wheel multifunctional

Seats electric F L Seats electric F R HD Central consol F Luggage cover Front parking sensors Rear parking sensors

Type of Tow bar

No Tow bar

110

Grey

ок

4812

Metalic

Aluminium

Seats F heated Radio multimedia Type of headlighting

Headlighting Xenon Type of GPS GPS big screen color Type of Lining Lining leather Type of climate control **Autom climate control**

Limited Technical Inspection

Airco functioning Battery functioning ок Yes Tires wear profile Power steering OK Yes Idle position oĸ Sound engine ок Clutch test Engine startingtime OK OK Exhaust gass Wiper fluid level OK OK Handbrake Transmission ок OK Lighting ок Wiperblades ок

Yes

Degree of wear

Summer tyres:

245/40/18/97 Y LightMetal				
Fr.L.	Goodyear: 6 mm	Fr.R.	Goodyear: 6 mm	
Re.L.	Continental: 6 mm	Re.R.	Continental: 6 mm	

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		
Total cost ex VAT			526.80

Total cost ex VAT	526,80
Seat cover F L, Deformed / Strained, Acceptable	0,00



Alloy rim F R, Scratch(es), LI - Repair and paint (complete)









Alloy rim R R, Scratch(es), LI - Repair and paint (complete)

95,00









Bumper F, Dent(s) and scratch(es), LI - Repair and paint (complete)

211,80







Interior, Dirty, Chemical cleaning

125,00







Alloy rim F L, Scratch(es), Acceptable	0,00
No pictures to display	
Tailgate, Dent(s), Acceptable	0,00

No pictures to display