


**FORD TOURNEO: 1VUR510**

|                                   |                          |              |                  |
|-----------------------------------|--------------------------|--------------|------------------|
| Vinnumber:                        | <b>WF0LXXTACLKC42514</b> | Versionname: |                  |
| First Registrationdate:           | <b>6/03/2019</b>         | Fiscalpower: |                  |
| Expertise Mileage:                | <b>10357</b>             | Power Kw:    | <b>55</b>        |
| Bodytype:                         |                          | Body color   | <b>Blue</b>      |
| Gearbox:                          | <b>MAN 6 VIT</b>         | Paint type   | <b>Metallic</b>  |
| Transmission:                     | <b>Front</b>             | Rims summer  | <b>Aluminium</b> |
| Fueltype:                         | <b>Diesel</b>            | Oil level    | <b>OK</b>        |
| Battery functioning               | <b>Yes</b>               | Parking lot  | <b>3212</b>      |
| Number of doors                   | <b>5</b>                 |              |                  |
| Number of seats                   | <b>5</b>                 |              |                  |
| Number head rests                 | <b>5</b>                 |              |                  |
| Rims summer                       | <b>Aluminium</b>         |              |                  |
| Category                          | <b>Passenger Car</b>     |              |                  |
| Oil level                         | <b>OK</b>                |              |                  |
| Registration Certificate Car (BE) | <b>Yes</b>               |              |                  |

**Options**

|                                |                              |                      |                   |
|--------------------------------|------------------------------|----------------------|-------------------|
| GPS storage                    |                              | Central consol F     |                   |
| GPS storage                    | <b>HD</b>                    | Luggage cover        |                   |
| Windows electric F             |                              | Rear parking sensors |                   |
| Cruise Control                 |                              | Type of Tow bar      | <b>No Tow bar</b> |
| Steering wheel multifunctional |                              |                      |                   |
| Seats F heated                 |                              |                      |                   |
| Radio multimedia               |                              |                      |                   |
| Type of headlighting           | <b>Headlighting Halogen</b>  |                      |                   |
| Type of GPS                    | <b>GPS big screen color</b>  |                      |                   |
| Type of Lining                 | <b>Lining fabrics</b>        |                      |                   |
| Type of climate control        | <b>Autom climate control</b> |                      |                   |

**Limited Technical Inspection**

|                     |           |                     |            |
|---------------------|-----------|---------------------|------------|
| Airco functioning   | <b>OK</b> | Battery functioning | <b>Yes</b> |
| Tires wear profile  | <b>OK</b> | Power steering      | <b>Yes</b> |
| Idle position       | <b>OK</b> | Sound engine        | <b>OK</b>  |
| Engine startingtime | <b>OK</b> | Clutch test         | <b>OK</b>  |
| Exhaust gass        | <b>OK</b> | Wiper fluid level   | <b>OK</b>  |
| Handbrake           | <b>OK</b> | Transmission        | <b>OK</b>  |
|                     |           | Lighting            | <b>OK</b>  |
|                     |           | Wiperblades         | <b>OK</b>  |

**Degree of wear**

|               |                                  |                |       |                |
|---------------|----------------------------------|----------------|-------|----------------|
|               | <b>195/55/16/87 H LightMetal</b> |                |       |                |
| Winter tyres: | Fr.L.                            | Goodyear: 7 mm | Fr.R. | Goodyear: 7 mm |
|               | Re.L.                            | Goodyear: 7 mm | Re.R. | Goodyear: 7 mm |

**Assistance equipment**

|                                          |          |
|------------------------------------------|----------|
| Number of charging cables (normal)       | <b>0</b> |
| Number of charging cables (rapid charge) | <b>0</b> |

|                                   |               |
|-----------------------------------|---------------|
| Total cost ex VAT                 | <b>158,85</b> |
| Door F L, Scratch(es), Acceptable | <b>0,00</b>   |




Door R R, Scratch(es), Acceptable 0,00



Bonnet, Stone chip(s), Acceptable 0,00

No pictures to display

Bumper R, Scratch(es), LI - Repair and paint (complete) 158,85



Door panel F L, Stain, Cleaning 0,00

