


MERCEDES C BREAK: 1LGK128

Vinnumber:	WDD2052361F274960	Versionname:	1.6 C 180 D
First Registrationdate:	22/09/2015	Fiscalpower:	
Expertise Mileage:	126391	Power Kw:	85
Bodytype:		Body color	Black
Gearbox:	MAN 6 VIT	Paint type	Metalic
Transmission:	Back	Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Maintenance	UITVOEREN	Parking lot	2806
Maintenance	NOT OK		
Battery functioning	Yes		
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options

Radio CD	Central consol F
GPS storage	Luggage cover
GPS storage	SD Front parking sensors
Windows electric F	Rear parking sensors
Windows electric R	Type of Tow bar
Cruise Control	No Tow bar
Steering wheel multifunctional	
Radio multimedia	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining fabrics
Type of climate control	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	NOT OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

Summer tyres:	205/60/16/92 V LightMetal			
	Fr.L.	Michelin: 6 mm	Fr.R.	Michelin: 6 mm
	Re.L.	Michelin: 5 mm	Re.R.	Michelin: 5 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	1238,83
Door R L, Scratch(es), LI - Repair and paint (complete)	318,35



Alloy rim R L, Scratch(es), Acceptable

0,00

No pictures to display

Maintenance, Maintenance, Execute

0,00



Bumper corner R L, Scratch(es), It - Spot repair

115,56



Door F L, Scratch(es), Acceptable

0,00

No pictures to display

Backrest cover F L, Worn, Acceptable

0,00

No pictures to display

Door frame F L, Scratch(es), Acceptable

0,00

No pictures to display

Door panel R L, Hole, Smart repair

110,64



Wing R L, Dent(s) and scratch(es), LI - Repair and paint (complete)

404,20



Bonnet, Stone chip(s), LI - Repair and paint (complete)

290,08

