


MERCEDES GLA: NB6861

Vinnumber:	WDC1569081J546406	Versionname:	GLA 200 d Business Solution
First Registrationdate:	17/08/2018	Fiscalpower:	
Expertise Mileage:	35579	Power Kw:	100
Bodytype:		Body color	Black
Gearbox:	Automatic	Paint type	Metallic
Transmission:	Front	Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Battery functioning	Yes	Parking lot	2706
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		

Options

Radio CD		Central consol F	
GPS storage	SD	Luggage cover	
GPS storage		Type of Tow bar	No Tow bar
Windows electric F			
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining semi-artificial leather		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

215/60/17/96 V LightMetal			
Summer tyres:	Fr.L.	Continental: 5 mm	Fr.R.
	Re.L.	Continental: 7 mm	Re.R.

Assistance equipment


Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	1644,75
Wing R R, Dent(s) and scratch(es), LI - Repair and paint (complete)	369,84



Bonnet, Chemical polution, LI - Repair and paint (complete)

348,09



Wing R L, Dent(s) and scratch(es), LI - Repair and paint (complete)

369,84



Wing F R, Chemical polution, 67 - Polish

0,00

No pictures to display

Door R R, Scratch(es), 67 - Polish

0,00

No pictures to display

Door R L, Scratch(es), 67 - Polish

0,00

No pictures to display

Floor covering F L, Hole, Smart repair

64,32



Door panel R R, Tear, Smart repair

110,64





Door F L, Scratch(es), LI - Repair and paint (complete)	382,02
---	--------



Rocker panel inner R R, Scratch(es), Acceptable	0,00
---	------

No pictures to display

Bumper R, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display